

Quality Control Check Repot. Stage: After Column Casting (villas)

Block No. 17	Column No.	0	Sl. No.	30684
Company Sov (LLP)	Project	SOV	Phase	<u>]</u> ×1
Prepared by P. Sen Kann	Sign	Rich	Date	21/9/18-6
Project Manager K. Sunhathen	Sign	A.	Date	29/6/18.
Previous stage report no.	30478	Report filed and signed by PM?	d by PM?	\Xes □No
Checked By MD on	MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	n QC report to QC team. Proo work after submitting ATR or ter making corrections pointe not required.	ceed only after recheck l n QC report to QC team ed out in the QC report.	by QC. ATR not required.	

Columns Position Check.

Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab.
- Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.

Columns Position Check Plan enclosed?

Stab Diffensions Check,

Notes:

- 1. Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of halconies (Tolerance 1")
 Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.

Quality Control Check Repot. Stage: After Column Casting (villas)

Ouality of centering, rod bending and concreting.		
Quality of centering, rod bending and concreting?		Good Avg. Bad
Quality of starters?		☐ Good ☐ Avg. ☐ Bad
Number and size of honey combs?		☐ High Medium. ☐ Lov
Are the honey combs is slab and columns packed?		☐ Good ☐ Avg. ☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than	than 1")
Have 6 cubes each for columns and slab casted and numbered for testing?		□Ýes □ No
Remarks:		
Bunds for curing made on slab?	☐Yes ☐No NA	ZP
Bund size is less than 100 sft?	☐ Yes ☐ No	la company
Drum (200 lts) provided for curing?	∏Yes □No	1
Gunny bags used for column curing?	☐Yes □No	•
Distance of tap from furthest distance that requires curing. (max permitted 100')	40.0"	
Frequency of curing in number of times a day (enquire from labourers)	2- times	
Is the pressure in the curing pipe more than 15' head?	Tyes No	
Quality of infrastructure for curing.	Good ☐ Avg.	Bad
Remarks:		

Columns height, plumb, steel & level marking check.

- Mark or for correct or minor mistake which does not require correction

 Mark or minor mistake that requires minor correction.

 Mark or major mistake that requires correction by replacement or re-fixing.

 Mark oo major mistake that cannot be corrected.

 Tolerance: Plumb 0.25".

20.	19.	18.	17.	16.	15.	14.	13.	12.	11.	10.	9.	0	7.	6.	5.	4.	'n	2.	 -			SNo
		1		1	<u>T</u>)	47	J.	プグ	フィ ・ ・	DI -	C3	2	1.0	B3	Br	731	A3	Az	<u>⊅</u>			Col No
	_				(3)	7	()	()	7	C1	CY	Cr	C)	0	2	C)	7	(" /	()		Cor type	Col type
				z =	_				8.41				マー・ヤー	1.4.8	x.4"	ν. .ν.	ا ا ا	• •	\$. \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		Spec	Uai
			2	. –	-	<i>,</i> \dashv	,	4	•	•	~				× 4.1	, -	ή σ_α		16.8	Temar	rieight in It	O Col No Col tyme Height in Specifica neight by more than I
					, k		3	,	, ,	, <				(5	5	5		5	rods	Steel (To mergin oy I
				•		<	5	,		< <	, <	``				<	ς,	,		Size of	Steel (v or x)	nore than 1.
			<	<	, <	, \	<						3 <	57	< <	\		4			Honeycombs	
			<	<	,	, ,	<	,	,	, (,	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	,	\			, <	, ,		Side 1	Plumb	
			_	<	<	K	K	<		, <	, <	, <	<	,	<		,	<		Side 2	Plumb (v or x)	
☐Yes ☐No	☐Yes ☐No	☐Yes ☐No	Yes No	Yes No			┧┌	1	1	7/	╗	7/1	┧┌	┧┌	1 -	1	╗	1/	┧゛	marked on	Reference level	