Company   Common   Project   Manager   Project   Project   Manager   Project   Project   Manager   Project   Proje						The second secon
pect    Phase   Phase   Date	Block No.	176	Column No.	<u>O</u>	SI. No.	313.79
Date    Color   Color   Date     Color   Color   Date     Color   Report filed and signed by PM?     Sign   For filling     to QC team. Proceed only after recheck by QC. ubmitting ATR on QC report to QC team.     corrections pointed out in the QC report. ATR not required.	Company	Niloisi Estates		vibisi Estates	Phase	Ħ
n    C22   Report filed and signed by PM?     Sign   For filling     to QC team. Proceed only after recheck by QC. ubmitting ATR on QC report to QC team.     corrections pointed out in the QC report. ATR not required.	Prepared by			Mrsh S.V	Date	81-60-40
No 22 Report filed and signed by PM?  Sign For filling  to QC team. Proceed only after recheck by QC.  ubmitting ATR on QC report to QC team.  corrections pointed out in the QC report. ATR not required.	Project Manager	madhis Misa		. 1	9	81-80-40
Sign For filling to QC team. Proceed only after recheck by QC. ubmitting ATR on QC report to QC team. corrections pointed out in the QC report. ATR not required.	Previous stage report	no.		Report filed and signe	PM?	Myes □No
to QC team. Proceed only after recheck by Qubmitting ATR on QC report to QC team. corrections pointed out in the QC report. ATR	Checked By MD on		MD Sign		For filling	☐Yes ☐No
	Recommendation: Stop further work. Stop further work. Proceed with furtl Proceed with furtl	Submit ATR on QC re. Proceed with work aft her work only after making work. ATR not required.	port to QC team. Proceer submitting ATR on ing corrections pointed ired.	ed only after recheck be QC report to QC team. I out in the QC report.	y QC.  ATR not required.	

## Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab.
- Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1") Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.

3. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention a	t dimension with red colour and mention actual dimension next to it.
Columns Position Check Plan enclosed?	☑ Ycs □ No

## Slab Dimensions Check.

Notes:

- 1. Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
  Show length and width of balconies (Tolerance 1") Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- 2. Slat į .

Specified thickness of slab?	Slab Dimensions Check Plan enclosed?	2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention a
Actual thickness of slab?	Yes No -	nension with red colour and mention actual dimension next to it.

## Quality Control Check Repot. Stage: After Column Casting (villas)

V Good   Avg.   Bad
Good Avg. Bad
] High ☐ Medium. ☑Lov
Good Avg. Bad
Yes ☐ No
] Bad

## Columns height, plumb, steel & level marking check.

Notes:

- Mark for correct or minor mistake which does not require correction
   Mark × for minor mistake that requires minor correction.
   Mark × for major mistake that requires correction by replacement or re-fixing.
   Mark × × for major mistake that cannot be corrected.
   Tolerance: Plumb 0.25".

6	
6. Circle actual height of columns if level differs from specified height by more than 1	
height of	
[columns i	
flevel	
differs f	
rom speci	
fied heigh	
it by more	
than I	
1.	•

1				
Stries	Z	2	2 4 4	2 4 4
Spirs	ب	2	2 4 4	5 4 4
11 4-18	2_	2	2 2 5	2 4 4
3/211	. Z	2	2	2 2 2
8-51	<	1	~ ~ ~	
8-611	~	1 1	~ ~ ~	4 4 4
1	4	1	1 1	
1,41	_	K .		
6 17	1	\ \ \	2	
8-3"	1	~ ~		
17.75	2	~		
1 =	<	<		
2	4	4 2	4 2 2	4 2 4
6 "	۲,	<u>ر</u> ر	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	X X X X
ro	rods	ds rods		
Actual No	No of		Size of	
Height in it	היהרו (		Troncycomes	Sign ( of X) Honeyconios