Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager Ma	Prepared by	Company	Block No /
	MD Sign	28848	§ 3		Nilvi Estates	177
			Sign	Sign	Project	1
		Report filed and signed by PM?	Mindel Date		Nilcini Estates	
by QC. ATR not required.	For filling	by PM?	Date	Date	Phase	Sl. No.
	☐Yes ☐No	NYes No	11-08-18	11-08-180	H	3113)

Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam

 Yellow enamel point to be used for marking FFL of flooring. Mark 2° above FFL on column steel. Plinth beam top must be 2°3 (in case of pavers) or 2°4" (in case of RCC slab) below the mark. Prepare plinth beam. Dimensions Check Plan as follows:

 a. Show outer dimensions (Lolerance 2°) b. Show length and width of plinth beams (Tolerance 1°) c. Print an A3 size plan.

 Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

ΡIi	(A)
nth Beam Dimensions Check Plan enclosed?	Project managers must make pedestal colum
lan enclosed?	in () self eheck report similar to report for ec
Yes No	Project managers must make pedestal column () self check report similar to report for column check. QC must collect report and attack
	ach the same to this report

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

|--|

Plinth Beam Steel check.

Zotes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XXX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	3.	2.	<u>.</u>	S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	<u> </u>	<u> </u>	4	√	4	<	4	Quantitative Check
	☐ Good ☑ Avg. ☐ Bad	☐ Good ¶ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good M Avg. ☐ Bad	☐ Good 🗹 Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	Qualitative Check (Good / Avg. / Bad)