Quality Control Check Repot. Stage: After Plastering (Villas)

Villa No.	481	Stage		SI. No.	33443
Company	VOC (LLP)	Project	Voc	Phase	1
Prepared by	G. RAJES H	Sign	Ehre ()	Date	20/4/19
Project Manager	A. Sures H	Sign	Y.	Date	20/4/19
Previous stage report no.	10.	32921	Report filed and signed by PM:	d by PM?	Nes □No
Checked By MD on		MD Sign		For filling	□Yes □No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	commendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after so Proceed with further work only after making of Proceed with further work. ATR not required	eport to QC team. Proofer submitting ATR or cing corrections pointe ired.	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required Proceed with further work. ATR not required.	by QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

<u>Plastering Check.</u> Notes:

- Mark for correct or minor mistake which does not require correction
 Mark if or minor mistake that requires minor correction.
 Mark if or major mistake that requires correction by replacement or re-fixing.
 Mark if or major mistake that cannot be corrected.
 Mark if or major mistake that cannot be corrected.
 9"unplastered area from SFL should be left including in common areas and terraces.
 Windows must be checked with templates. Tolcrance ¼".
 Provision of tiles in bathrooms, kitchen & wash areas (rough plastering).
 Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Rer	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	-	S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony-2	_	Lobby 2 F. Louise		Dining	Drawing	Toilet 4	Bedroom-4	6.	Bedroom 3 G.B		Bedroom 2 C. B		Bedroom 1 M.B	Room
		1	<	١	<]		<	7	<	<	1	1	<	<	<	<	7	7	Skirting Provision (v or x)
		١	<	١	<)	~	<	<	<	×	,)	V	7	7	7	7	K	Finishing around do frame (v or x)
		١	<	١	~	١	<	<	1	<	7	١)	<	<	<	<	7	7	Beams & columns finishing (v or x)
		1]	١	*	١	١	ļ	1	ı	1	1	١	1	1	1	1	1	l	Finishing of lofts (v or x)
		1	\	1	<	١	~	<	/	/	7	-	١	7	7	\	7	<	7	Electrical junctions finishing (v or x)
		١	7	1	<	١	1	1	V	1	V	•)	<	<	<	<	<	\	Window check (• or ×)
		*****	7	1	١	1	١	١)	1	}	١	١	7	1	<	ĵ	<	1	Tiles provision (✓ or ×)
		١	,	1	,	1	1]	1	1	1	١	7	ı	١	١	1	1	1	Sink provision & sin(or x)
]	<	1	<	١	<	<	7	7	3%	١	ו	<	<	<	<	7	×	Grooves for door frames (v or x)
		١	١	1		١	7	1	1	1	1	1)	ſ	I	(l	(1	Balcony & terrace s top finishing 10 (v or
		1	1	3	I	1		1	<u> </u>	1	1	١	7	7		<	1	7	1	Screeding in bathrow & utility (v or x)
		1	1	1	1	1	Ţ	1	١	-	١	1)	<	1	<	1	<	1	Screeding in 6" above FFL? (• or ×)

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	☐ Good ☑ Avg. ☐ Bad
Plastering of compound wall & gate pillars (v or x)	
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	☐ Yes ☑No
Plastering quality of parapet walls (v or x)	×
Plastering and finishing of chajjas (v or x)	
Remarks:	
,	