## Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATP Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Villa No.
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. AT Proceed with further work. ATR not required.		10.	A- Sumosh	V. Cambeth	(911) Joh	188
port to QC team. Proceed ter submitting ATR on the corrections points ired.	MD Sign	32685	Sign	Sign	Project	Stage
eed only after recheck QC report to QC team d out in the QC report.		Report filed and signed by PM?	Cy.	V-Baket	Voc.	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	☐ Yes ☐ No	√Yes □No	26/04/19	26/04/19	P	33473

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

### Plastering Check,

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.

  Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance ¼".

- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- 98798489 All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

<<

12

14 13

Terrace / balcony 1
Terrace/-balcony 2

Head room

Utility Other

Portico Kitchen

1 1

î

10

Dining

Lobby 1

Bedroom 4
Foilet 4

1

Bedroom 3

EST.

j

) 1

}

Bedroom 2 Toilet 2

Toilet 3

Toilet 1

975

S No

Room

**Skirting Provision** 

frame ( v or X)

Beams & columns

finishing (✓ or 🗙)

Tiles provision

Sink provision & size

Balcony & terrace sill

top finishing  $^{10}(\checkmark \text{ or } X)$ 

Screeding in bathroom & utility ( or x)

Screeding in 6" above

FFL? (v or x)

Grooves for door

frames ( v or x)

( ✓ or X)

( v or X)

Finishing around door

( ✓ or X)

	9
ĺ	Ø
	O
	2
	0
	f
	w

# Quality Control Check Repot. Stage: After Plastering (Villas)

MISCENIALEOUS CHECK	•
Overall quality of plastering?	☐ Good ☑ Avg. ☐ Bad
Plastering of compound wall & gate pillars ( v or x)	to
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Yes No
Plastering quality of parapet walls (✓ or 🗙)	<u> </u>
Plastering and finishing of chajjas (v or x)	
Remarks:	