v	Quality Con	Quality Control Check Repot.	Stage: After Brickwork (Villas)	
Bungalow No.	20	Others	Sl. No.	32805
Company	Sov(TUR)	Project	Soy Phase	
Prepared by	N Samketh	Sign	TELEST Date	02-02-19
Project Manager		Sign	Date	02-02-19
Previous stage report no.	no.	31373	Report filed and signed by PM?	¬Yes □No
Bungalow No		Other	Other	
Checked By MD on		MD Sign	For filling	☐ Yes ☐ No
Recommendation:	Submit ATR on OC re	port to OC team Proc	Recommendation: [7] Ston further work Submit ATR on OC report to OC team Proceed only after recheck by OC	
Stop further work.	Proceed with work af	ter submitting ATR on		
Proceed with furth	ıer work only after mak	ring corrections pointed	Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	3
Proceed with furth	Proceed with further work. ATR not required.	ired.		

Inspection should be done after:

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed
- electrical conducting work is completed (except bathrooms).

Brickwork Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- Check room height with specified height. (Tolerance: 1") Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.
- Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL
- Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 screws.

Ren	19	18	17	16	15	14	13	12	Ξ	10	9	8	7	6	2	4	, L	1		S No
Remarks	Other:	Utility	Kitchen	Portico	Head room	Ferrace / balcony 2	Terrace/-balcony 1	Eobby-2 -	Lebby-1	Dining	Drawing	Toilet 4	Bedroom 4	Töllet3	Bedroom-3	Toilet 2 C-Tci	Bedroom 2 水、B		Bedroom I M. 13	Room
			×,	ı	4	1	1	١	Ą	Ł	<	٠,	١	ì	l	<	<	Z	<	Wall thickness
			4	J	AVS].	1	1	1	<	<	1	Ī	1	ı	1	4	<	<	Beds in walls (v or x)
			<	ı	<	1	١	1	,	<	٧.	1	ì	1	1	۷	<	K	\	Chicken mesh (✓ or 🗙)
			۷.	1	<	\$20a	١	1	1	<	<	1	1	1	1	۷.	<	<u> </u>	Ý	External brickwork & beam joint (or x)
			<	1	4	•	1	1	1	< .	<	•	1	ì	P	<	<	<	<	Room Dimensions (v or x)
			۷.	ľ	४	1	١	9	1	<	٠,	1	1	1	١	<	<	<	<	Room Dimensions Difference in inches
			<	1	<	ľ	1	,	١	<	<	1	1	١	7	<	<	1	4	Diagonal (v or x)
			<	,	<	ı	١	,	1	۲	<	1	P)	1	<	<	<	~	Diagonal Difference in inches
			٩	ļ	P	1	١	1	1	7 }		,	,	· ·	٩	7	ì	ן	١	Balcony sill level
		,	<	,	4	I	١	1	١ .		<	1	!	٦	,	<	4	1	۷	Room Height (• or ×)
			D'S	Ì	AVB	1		-	, :	11	ring.	7		1	P	: S	mood	=	Ava	Plumb of walls (Good/Avg./Bad)
			٤	7	•	1	e Films		1	<	<	40	1	7	4		<	۲ ا	<	Alignment of beams and walls - Nos.

	Quality Control Check Repot.		Stage: After Brickwork (Villas)	
Quality of edges and corners in all rooms?	ners in all rooms?	Good Avg. Bad	Avg. Bad	
Specify rooms that need correction:	correction:	ì		
Chajjas Quality Check Notes: Width of chajja should	Chajjas Quality Check Notes: Width of chajja should be 6"more than the width or the door or window.	oor or window.		
Total Nos. of Chajjas	Slopes incorrect – nos.	Slopes incorrect – nos. Thickness incorrect – nos Width inco	Width incorrect - nos.	Height in correct - nos
S	4	<	<	<.
Kemarks				

Door Frames & Windows check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark X X for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering.
- Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 32"or 33" from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points.
- Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

Ren	19	78	10	5 6	15	14	13	12		10	9	∞	7	0	5	4	ယ	2	-	S No
Remarks:	Other	Other	Kıtchen	Portico	Head room	Terrace / balcony	Terrace/-b	Lobby 2	Lobby 1	Dining	Drawing	Feilet 4	Bedroom 4	Toilet 3	Bedroom-3	Toilet 2	Bedroom 2	Toilet I	Bedroom	
					n	balcony 2	Terrace/-balcony 1-						4					M-701	1 MIB	
			2	1	۷	1	1	1	-	1	۲,	ì	1	1	•	· ·	<	<		Door size, face and position (vor X)
			<	f	۷.	1	١	1	1	t	<	1	1	1	1	<	•	\		Brick at bottom of door frame10 (✓ or 🗙)
			<	1	<	7	1	1	١	١	ς.	1	1	1	1	<	<	7	۷	Door lentil level ⁶ (• or ×)
			<	7	<	1	١	1	1	1	<	1	•	1	1	<	(<	۷ .	Door diagonal check ⁶ (✓ or 🗙)
		-	<	Ì	Ļ	1	١	1	١	4	<	1	1	1	1	<	`		- 1	Door Plumb - two sides (vor X)
			<	1	<	1	1	1	\	1	<	1	1	ļ	1	`			,	Door frame black Japan/wood primer/Peelambar check (vor x)
			,	1	,	1	٦	1 1		۲,		7	1	1	١.	٠,		٢.	۷	Windows lentil & sill level(✓ or 🗙)
			<	1	1	1	,	, !			۲	1)	١	1	٢,	۲ (۷ .	Windows size (✓ or 🗙)
			<	9	1	1)	١	1	,		1	1	1	1	<		`	ر د	Windows - template depth & diagnal ⁵ (✓ or 🗙)
			<	1	١	1	3	, l	•		(1	1.	1	1	۷ .			r	Windows - template powder coated ⁵ (v or ×)
			r Se	7	!	,	7	1 ,		9	!	1	,)	}	۱ ۱				oft & Kitchen platform equired ? (Yes or No)
			٩	1	1	١.)	1 1		1	1	1)	,	١	†			p	Loft & Kitchen platform provided ⁸ (✓ or 🗶 or JA)
			<)	}	7	١)		١	(9	9	1	1 1		L	oft & Kitchen platform lope (v or X)

Quality Control Check Repot. Stage: After Brickwork (Villas)

		Kemarks:
~~	xide painting (or x)	Parapet and compound wall railing design quality, fitting & redoxide painting (or x)
<		Parapet wall thickness, height and design (or x)
\ \		Chicken mesh provided on external joints of villa (or x)
Actual distance provided: 1011	1010"	Specified distance between gate columns:
Actual height provided: 400"	410"	Specified height of gate columns:
✓Yes □No	ove FFL?	Is level marked on villa & compound wall with 2 screws, 2 ft above FFL?
✓ Yes □No		Is leveling in the setbacks of the villa 6" below FFL?
✓ Good ☐ Avg. ☐ Bad		Quality and level of PCC for portico?
Good ☐ Avg. ☐ Bad		Quality and level of PCC on ground floor?
Actual level above FFL: 3-6"	326"	Specified compound wall height above FFL:
Actual level below FFL: -	_	CRS + bed - specified level below FFL:
		Compound wall check
		Remarks:
	✓ Yes □ No	Drum (200 lts) provided for curing in each flat?
	☐ Good ☑ Avg. ☐ Bad	Storage of building material like bricks sand and cement.
	☐ High ☑ Medium ☐ Low	Wastage?
	Yes □No	Is the Bungalow cleaned for plastering?
ıy	☐Yes ☐ No ☑ Cant' say	Was the Bungalow cleaned before starting brick work?
	☐ Good ☑ Avg. ☐ Bad	Condition of proportion box?
	✓ Yes □No	Was 3.75 CFT proportion box provided?
		IVIISC: CHECKS.