Quality
Control (
Quality Control Check Repot. Sta
Stage: After Column Casti
olumn (
Casting (
villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on MD Sign	Provious stage report no. 31876	Project Manager A. S. Sign	Prepared by V. Sankoth Sign	Company Voc (119) Project	Block No. 212 Column No.
OC team. Proceed only after recheck builting ATR on QC report to QC team. rrections pointed out in the QC report.		Report filed and signed by PM?	\{\frac{\frac{1}{2}}{2}	1.0x2	ot VeC	nn No. 02
by QC. ATR not required.	For filling	d by PM?	Date	Date	Phase	SI. No.
	Yes No	✓Yes □No	टा/प्रांध	0/12/18		32260

Columns Position Check.

Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab. Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.

Columns Position Check Plan enclosed?	3. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention
Yes No	Sh incorrect dimension with red colour and mention actual dimension next to it.

Slab Dimensions Check.

Notes:

- 1. Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
 Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.

Ω	
Ξ.	
÷	
Ö	
rcle each c	
Ħ	
9110	
<u>@</u>	
끜	
d.	
3	
G	
S.	
2	
7	
≦.	
Ħ	
19	
sion with green colour. Circle	
급	
0	
으	
2	
F	
Circle each incorn	
Ç	
O	
ea	
Ch	
Ξ.	
5	
ë	
7	
7	
<u>G</u>	
ct d	
ct din	
ct dime	
ct dimens	
ct dimensic	
ct dimension	
ct dimension w	
ct dimension with	
ct dimension with 1	
ct dimension with rec	
ct dimension with red	
ct dimension with red co	
ct dimension with red color	
sion with red colou	
ct dimension with red colour as	
sion with red colou	
sion with red colou	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	
sion with red colou	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	
sion with red colour and m	

U	/ 10than allowness of side.	Specified inferriess or state:
า =	Actual thickness of clah?	1
	I GS LINO	Slab Dimensions Check Plan enclosed?
		21 1 10
actual difficustoff next to 11.	histon with red colour and mention actual diffici	2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and incident

Quality Control Check Repot. Stage: After Column Casting (villas)

CLOVERD.	nor the tooker but are
)
Bad	Quality of infrastructure for curing.
	Is the pressure in the curing pipe more than 15' head?
	Frequency of curing in number of times a day (enquire from labourers)
	Distance of tap from furthest distance that requires curing, (max permitted 100') 30-0"
	Gunny bags used for column curing?
	Drum (200 lts) provided for curing?
	Bund size is less than 100 sft? ✓ Yes No
	Bunds for curing made on slab?
	Curing.
	Remarks:
Yes No	Have 6 cubes each for columns and slab casted and numbered for testing?
1	Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"
☑ Good ☐ Avg. ☐ Bad	Arc the honey combs is slab and columns packed?
☐ High ☐ Medium. ☑ Low	Number and size of honey combs?
Good Avg. Bad	Quality of starters?
☐Good ✓ Avg. ☐ Bad	Quality of centering, rod bending and concreting?
	Oliality of centering, rod bending and concreting

Columns height, plumb, steel & level marking check. Notes:

- Mark v for correct or minor mistake which does not require correction Mark x for minor mistake that requires minor correction.

 Mark x for major mistake that requires correction by replacement or re-fixing. Mark x x for major mistake that cannot be corrected.

 Tolcrance: Plumb 0.25".

 Circle actual height of columns if level differs from specified height by more than 1".

20.	19.	18.	17.	16.	15.	14,	13.	12.	11.	10.	9.	.8	7.	6.	5.	4.	in	2.	1.			SNO
									D3	0,	C4+	C_3	5	134	B2	33)	A4	H3	A)			Col No.
									£	CL	CS	8	C		42	2	2	500	2			Col type
									91-1"	814"	8-4"	8-4"	Staios	8-1:	9111	Staiss	= 12-6	1478	16.78		Spec.	Heig
									8-11	8-3"	8-3"	8154	इक्लंड	8-311	8-3"	Stares.	11:78	815"	8- q"		Actual	Height in st
									<	K	<u> </u>	<	<	<	<	۷.	۷,	۷	く	rods	No of	Steel
									<.	ζ.	4	<	<	۷.	<	<	<	۷.	۷.	rods	Size of	Steel (v or x)
					THE COLUMN TWO COLUMNS TO THE COLUMN TWO COLUMNS TWO COLUMNS TO THE COLUMN TWO COLUMNS TO THE COLUMN TWO COLUMNS T				۷,	<	<u> </u>	<	•	~	4	(<	4	۷.			Honeycombs
				0 - 63					<	<	<	<		~	٧	く	V	J	V		Side 1	Plumb
									<	<_	<	~	1	~	<	۷	4	~	~		Side 2	Plumb (or x)
☐Yes ☐No	☐ Yes ☐ No	☐Ycs ☐No	☐Yes ☐No	☐Yes ☐No	☐Yes ☐No	☐Yes ☐No	☐Yes ☐No	☐Yes ☐No	Yes No	Yes □No	Yes No	Yes No	Yes No	✓ Yes □No	✓ Yes ☐ No	Yes No	✓ Yes □ No	✓ Yes ☐ No	✓ Yes ☐ No	column?	marked on	Reference level