

Checked By MD on Previous stage report no. Project Manager Recommendation: Prepared by Company Block No Proceed with further work. ATR not required. Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Quality Control Check Repot. Herens H V. Sanketh くろ 214 (ILp)MD Sign 30004 Sign Sign Project 1 Stage: Before Casting Plinth Beam (Villas) Report Illed and signed by PM? You Phase For filling Date SI. No. 25-08-18 ∐Yes [Yes UNO 25-08-18 31268 ١ Zo

Plinth Beam Check.

- Inspection should be done before casting of plinth beam.
- Yellow enamel paint to be used for marking FFL of flooring. Mark 2" above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark Prepare plinth beam. Dimensions Check Plan as follows.
- Show outer dimensions. (Tolerance 2")
- Show length and width of plinth beams (Tolerance 1")
- Print an A3 size plan
- 'J. + Circle each cerree, dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it
- Project managers must make pedestal/column 0 self-check report similar to report for column check. QC must collect report and attach the same to this report

Γ	고
	inth
İ	Bea
ĺ	
	ime
	nsio
	ns C
	hec
	(Pla
	ın en
ì	clos
	ed?
**	
-	
	XXXX
	es
	Vo
	Ì

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

			Remarks:	Pedestal/column0 – self check report attached?	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Level marking at 2' above FFL is made?	Brackets for elevation features provided?	Alignment of beams on outer side?	Quality of Bracing Provided?	Have rods for staircase slab been provided?	Quality of centering, rod bending and concreting?	Quality of centering, rod bending and concreting.
	The state of the s			Nyes □No	Correct Needs correction	⊠Yes □ No	☐ Yes ☐ No [YNA	☐ Good ► Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Yes No	Good MAvg. Bad	

Plinth Beam Steel check.

- 1. Mark for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XXX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	3.	2.	-	S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	~	~	~	1	1	1	~	Quantitative Check
	Good • Avg. ☐ Bad	☐ Good M Avg. ☐ Bad	Good Avg. Bad	☐ Good Avg. ☐ Bad	Good Avg. Bad	Good Avg. Bad	Good Avg. Bad	Qualitative Check (Good / Avg. / Bad)