Quality (
Control Che
Quality Control Check Repot.
Stage: Before Casting Slab (Villas)
Stage: Before (
Casting
Slab
(Villas)

nac (ICA)	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.
	Ldes led and signed by PM
	A · Swash Sign W Date 32813 Report filed and signed by PM? MD Sign For filling
S. Rulder Sign Alider Date	32813 Report filed and signed by PM? MD Sign For filling
S. Ruldelp Sign Studens Date A. Surash Sign W Date	MD Sign For filling
S. Ruldeep Sign Date A. Susesh Sign Uw Date 32813 Report filed and signed by PM?	

Slab Check. Notes:

- i. Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.
 2. Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- Show inner dimensions of ducts. (Tolerance 1") Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL: Check staircase of lower floor that has been easted. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Slab Dimensions Check Plan enclosed?	;d?		Yes No	No		
Staircase - mid landing!	Specified ht:	١	Actual ht:	1	Within tolerance of 1/2"?	Yes No
Staircase - mid landing 2	Specified ht:	1	Actual ht:	١	Within tolerance of 1/2"?	☐Yes ☐No
Staircase width	Specified wd:	1	Actual wd:	1	Within tolerance of 1/2"?	☐Yes ☐No
Staircase slab thickness	Specified:	•	Actual:	1	Within tolerance of 1/4"?	Yes No

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Remarks:

Slab Steel check. Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

1
``
<
ζ.
(
ζ.
<
ζ.
ζ.
<
ζ
7
,
′
Quantitative Check