Block No 22		Quality Control Check Repot.	ı	Stage: Before Casting Plinth B	Beam (Villas)	
Project AGH Phase Project AGH Phase Sign Report filed and signed by PM? Butter MD Sign Report filed and signed by PM? For filling Coreced with work after submitting ATR on QC report to QC team. Work only after making corrections pointed out in the QC report. ATR not required.	Block No	27	1		Sl. No.	7 9 9 7 4
Suman Lunar Sign Report filed and signed by PM? But Report filed and signed by PM? For filling Cocced with work after submitting ATR on QC report to QC team. But Report filed and signed by PM?	Company	HPM (LLP)	Project	Aur	Phase	1001
Suman Junar Sign Report filed and signed by PM? MD Sign MD Sign MD Sign For filling bmit ATR on QC report to QC team. Proceed only after recheck by QC. occed with work after submitting ATR on QC report to QC team. work only after making corrections pointed out in the QC report. ATR not required. work. ATR not required.	Prepared by		Sign	Pro	Date	7
MD Sign Report filed and signed by PM? [For filling] bmit ATR on QC report to QC team. Proceed only after recheck by QC. occed with work after submitting ATR on QC report to QC team. work only after making corrections pointed out in the QC report. ATR not required. work. ATR not required.	Project Manager	4	Sign	THERE	Date	2012
MD Sign For filling ITHE Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Previous stage report no.			Report filed and signed by I	PM?	Yes No
ork. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Checked By MD on		MD Sign		For filling	☐Yes ☐No
	Recommendation: Stop further work. Sub Stop further work. Pro Proceed with further w	mit ATR on QC report to Q oceed with work after submi ork only after making corre ork. ATR not required.	C team. Pro itting ATR o	ceed only after recheck by Qon QC report to QC team.	C.	

Quality Control Check Repot.

Plinth Beam Check,

- Inspection should be done before custing of plinth beam.
 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam Dimensions Check Plan as follows:

- 4. a. Show outer dimensions. (Tolerance 2")
 b. Show length and width of plinth beams (Tolerance 1")
 c. Print an A3 size plan.
 Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Plinth Beam Dimensions Check Plan enclosed?
\\\\\Yes \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good [√Avg. ☐ Bad
Have rods for staircase slab been provided?	□Yes □No
Quality of Bracing Provided?	☐ Good ☐ Avg. ☐ Bad
Alignment of beams on outer side?	☐ Good ☑ Avg. ☐ Bad
Brackets for elevation features provided?	□Yes □No ☑NA
Level marking at 2' above FFL is made?	√Yes □No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	✓ Correct Needs correction
Remarks:	
	and the second s

Plinth Beam Steel check,

Notes:

- Mark \checkmark for correct or minor mistake which does not require correction Mark \times for minor mistake that requires minor correction.

 Mark \times for major mistake that requires correction by replacement or re-fixing. Mark \times for major mistake that cannot be corrected.

 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

	Remarks;		1 i	6	5.	4.		n i	3	1	S No
		Depth and width of beams	Covering Olocks for Deams	Covering Hools for 1	Steel Check - Reams Bearing	Steel Check - Beams Overlapping & Cranking	Sieel Check - Beams Extra Bars	Sicci Check - Beam size of bars	Steel Cheel Development of 1908	Steel Check - Room to of to de	Item
				<	<			< .	<	(or X)	Quantitative Check
		☑ Good ☐ Avg. ☐ Bad	Good VAvg. Bad	✓ Good ☐ Avg, ☐ Bad		V Good Ave Rad	_УGood ☐ Avg. ☐ Bad	Good Avg. Bad	Good Avg. Bad	(Good / Avg. / Bad)	Qualitative Check