Quality Control Check Repot. Stage: After Brickwork (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	Bungalow No	Previous stage report no.	Project Manager A. SURCSIA	Prepared by $G \cdot RD \cdot SCSIA$	Company YOC (LLP)	Bungalow No. 225
Oreport to QC team. Pr rk after submitting ATR making corrections poir required.	MD Sign	Other	32536	Sign	Sign	Project	Others
oceed only after recheck on QC report to QC tean ited out in the QC report.			Report filed and signed by PM?	C E	Olde	VOC	
by QC. a. ATR not required.	For filling	Other	ed by PM?	Date	Date	Phase	Sl. No.
	∐Yes ∐No		Yes No	26 lou 119	26 04 19	1	33469

Inspection should be done after:

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed
- electrical conducting work is completed (except bathrooms)

kwork Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- 11. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 12. Check room height with specified height. (Tolerance: 1") Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 14. Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar -- at cost of painter.
- Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL.
- Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 screws.

Rem	19	18	17	16	15	14	13	12		10	9	8	7	6	5	4	ယ	2	1	S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony-2	Terrace/ balcony 1	Lobby-2	Lовby 1	Dining	Drawing	Toilet.4	Bedroom-4		Bedroom 3 G.B	¥	Bedroom 2 (. ß	3	Bedroom 1 M. B	Room
			7	5	7,	1	7	1	5	5	<	1	7.4	5	7	<	<	<	5	Wall thickness (✓ or ×)
			<	<	<	1	<		<	<	<	1	1	۲	<	7	<	ς,	7	Beds in walls (v or x)
			<	<	<	-	<	1	<	<	<	١	1	<	7	7	<	<	7	Chicken mesh
			<	<	<	١	\	ı	<	<	<	1	١	<	<	<	<	?	<	External brickwork & beam joint (• or ×)
		ļ	<	*	<		<	1	<	<	<	١]	<	<	<	<	<	<	Room Dimensions (• or ×)
				A.	<	1	7	1	>	5	<	1	P	<	5	< '	<	<	<	Room Dimensions Difference in inches
				*	<	١	<	1	<	<	7	1	•	7	<		\	<	5	Diagonal (• or ×)
			<	1	<	1	7	}	<	<	<	1)	7	<	1	<	_	\	Diagonal Difference in inches
		12,5100 (1	ţ	1	*	1	<	7	١	1	l	ł.	١	l	١	!	ľ	l	1	Balcony sill level (or x)
			<	\	~	Ţ	<	7	<		<	1)	<		<	<	<	\	Room Height (• or ×)
			<	1	<	١	_]	<		<	1	?	<	<	۲		<	<	Plumb of walls (Good/Avg./Bad)
				1	<	1	<	1	7	<	7	!)	7	<	<u>,</u>	7	5	5	Alignment of beams and walls - Nos.

Specify rooms that need correction: Quality of edges and corners in all rooms? Quality Control Check Repot. Stage: After Brickwork (Villas) Good Mayg. Bad

Chajjas Quality Check

Notes: Width of chajja should be 6"more than the width or the door or window.

Total Nos. of Chajjas	Slopes incorrect – nos.	Slopes incorrect – nos. Thickness incorrect – nos Width	Width incorrect - nos.	Height in correct - nos
ယ	\	7	7	7
Remarks				
		Tr. market		
			ether financial services of the services of th	

Door Frames & Windows check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- 2. Mark X for minor mistake that requires minor correction.
- 3. Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 1/2" after plastering.
- 5. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 32" or 33" from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points.
- Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

Ren	19	18	17	16	15	14	13	12	11	10	9	∞	7	6	5	4	W	2	hend	S No
Remarks:	Other	Other	Kitchen	Portico	Head room	Terrace / balcony 2	Terrace/ balcony	Lobby-2	Lobby 1 Possa	Dining	Drawing	Toilet 4-	Bedroom 4.	2	n3 6.	·	Bedroom 2 C.	\$	Bedroom 1 M.	Room
			<	4	5	2 . ~	1 ~ ~	Į,		4	7	•		J.	BV	1 V	B V	-1 	B	Door size, face and position (v or X)
Salah IAN			<	1	<		<	}	<	4	5	,	,	<	<	7	<	く		Brick at bottom of door frame10 (✓ or 🗙)
			\	1	<	-	<	}	<)	<	1)	۲.	7	<	7	7	7	Door lentil level ⁶ (• or ×)
			<	1	7	1	<	1	<	١	<	-	1	V	4	7	<	<	7	Door diagonal check ⁶ (✓ or 🗙)
			<	1	ν,	•	~	1	7	١	~	1	1	<	<	7	7	ζ	•	Door Plumb - two sides
			<	1	< .	١	V		-	١	ζ,	ļ	}	7	<,	ヘ	<	7	1	Door frame black Japan wood primer/Peelambar check (vor X)
			<	1	ς.	١	<	1	7	~	N)	~	7	/	<	7	7	Windows lentil & sill level(✓ or 🗙)
			<	1	7	Ţ	<	1	7	<	ζ.	-)	<	7	<	<	<	V	Windows size (✓ or 🗙)
			7	1	ζ.	١	/	J	<	ζ.	7		1	7	۲	<	<	<		Windows - template depth & diagnal⁵ (✓ or 🗙)
			7	١	7	1	7	1	7	<	′ ′	1	}	<	7	7	<	7		Windows - template powder coated ⁵ (✓ or X)
			l		l	1	۱)	١	1	(1)	l	į	ı	1	1		Loft & Kitchen platform required ? (Yes or No)
			1	1	1	1	1	1	1	1	1	1)	١	(1	١	}		Loft & Kitchen platform provided ⁸ (✓ or 🗙 or NA)
		2000000	l		1	١	1	1	ţ	1	1	Ţ)	1	l	ı	1	1		Loft & Kitchen platform slope (v or X)

Quality Control Check Repot. Stage: After Brickwork (Villas)

Was 3.75 CFT proportion box provided?	
Condition of proportion box?	
Was the Bungalow cleaned before starting brick work? ☐ Yes ☐ No ☐ Cant' say	say
Is the Bungalow cleaned for plastering?	
Wastage? ☐ High ☐ Medium ☐ Low	4
Storage of building material like bricks sand and cement. Good Avg. Bad	
Drum (200 lts) provided for curing in each flat?	
Remarks:	
Compound wall check	
CRS + bed - specified level below FFL:	Actual level below FFL:
Specified compound wall height above FFL:	Actual level above FFL: 3
Quality and level of PCC on ground floor?	☐Good ☐ Avg. ☐ Bad
Quality and level of PCC for portico?	Good ☐ Avg. ☐ Bad
Is leveling in the setbacks of the villa 6" below FFL?	L Yes □ No
Is level marked on villa & compound wall with 2 screws, 2 ft above FFL?	[☐Yes ☐ No
Specified height of gate columns:	Actual height provided: —
Specified distance between gate columns:	Actual distance provided:
Chicken mesh provided on external joints of villa (vor x)	1
Parapet wall thickness, height and design (v or x)	
Parapet and compound wall railing design quality, fitting & redoxide painting (or x)	×
Remarks: Note: 1. Gate Columns Ove not Casted	