	Quality Control Check Repot.	Stage: Before Casting Plinth Beam (Villas)	
Block No	276 -	Sl. No.	7 0 0 0
Company	NEC (LL) Project	V/CC Phase	1000
Prepared by O	O, C: In Sign	Date)
Project Manager	Sign Sign	Date	3113118
Previous stage report no.	2 2 2 2	Report filed and signed by my to	3113/18
	59767.	Report filed and signed by PM?	Yes No
Cnecked By MD on	MD Sign	For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck	R on QC report to QC team, P	roceed only after recheck by OC.	
Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	ith work after submitting ATR y after making corrections point not required.	roceed only after recheck by QC. on QC report to QC team. Ited out in the QC report. ATR not required.	

Plinth Beam Check.

- Inspection should be done before casting of planth beam Yellow channel paint to be used for marking FFL of Hooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. It is show outer dimensions. (Tolerance 2")

 b. Show length and width of plinth beams (Tolerance 1")
- Plinth Be

Quality of centering, rod bending and concreting. Quality of centering, rod bending and concreting? Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Plinth Beam Steel check			Remarks:	Pedestal/column0 - self check report attached?	Column steel overlapping and cranking? (overlapping length should be 45 to 50 T)	Level marking at 2' above FFL is made?	Brackets for elevation features provided?	Alignment of beams on outer side?	Quality of Bracing Provided?	Have rods for staircase slab been provided?
			\\\Yes \ \No	Correct Needs correction	Yes No	Yes No NA	☐ Good N Avg. ☐ Bad	Good Avg. Bad	Yes No	☐ Good ☐ Avg. ☐ Bad

Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark x for minor mistake that requires minor correction.
 Mark x for major mistake that requires correction by replacement or re-fixing.
 Mark x x for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.		7	4.	3.	2.		<u> </u>	SNo
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Stool Ct. 1 P. Stool Cranking	Steel Check - Reams Ownlands & Co.	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Swel Check - Beam no of rods	Steel Charle December 1	Item
(<,	<	<			<	(v or X)	Onantitative Check
Coon Javes. Dad	Good Avg. Bad	Good Nor Bad		Good Avg. Bad	Mood Avg. Bad	Ly Ovou Avg. Bad	Cod A	Sood Avg. Bad	(Good / Avg. / Bod)	