Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	r repared by	Company	Villa No.
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.		no.	K. Kinhodhan	P. Sai, Kun	Sevi (LLP)	28
eport to QC team, Proc ter submitting ATR on ting corrections pointed tired.	MD Sign	32806	Sign .	Sign	Project	Stage
eed only after recheck QC report to QC team d out in the QC report.		Report filed and signed by PM?	to.	Divid,	Sov .	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	☐ Yes ☐ No	NYes □ No	28/2/19	28/2/19	(Sec.)	33040

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring:

Plastering Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.

 9"unplastered area from SFL should be left including in common areas and terraces.
- 6. Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering).
 Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- 9. All doors frames should have ½"grooves.
- 10. Sill top must be of uniform thickness, correct height, at one level & without broken edges.

		Ren	19	18	17	16	15	14	13	12	11	10	9	8	7	6	S	4	lω	2		S No
		Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony 2	Terrace./-balcony	Lobby 2	Lebby	Dining	Drawing	Toilet-4	Вефення 4	Toilet-3	Bedroom,3		n 2		Bedroom 1	
								ny 2	ву 1									7	S	MA	75	
	84			1	<	}	<	1	١	1	1	X	X)	Ī	•	<	5	7	<	Skirting Provision (• or ×)
	:			Í	٢	j	<	1	}	Ţ	1	1	<		}	1	{	<	5	5	5	Finishing around door frame (• or ×)
				[<	ς	<u> </u>		4	1	1	<	<	1)		1	<	ζ.	5	7	Beams & columns finishing (v or x)
	8			\	<	J	J	- market	1	\	}	-	1	Ì	}	}	1	{	{	(1	Finishing of lofts (• or ×)
				1	<	<	<	1	1	ŗ	}	<	<	-		Ī		ς.	Х	<	<	Electrical junctions finishing (v or ×)
				J	7	}	<	1]	3)	<	5	1	}	}]	<	<	5	5	Window check (✓ or ×)
				1	<	(J	1	1)	1	ſ	}	1	1	{)	<	1	<	{	Tiles provision (v or x)
		-		1	<	J	j	(1	}]	1	}	1		1	}	<	\	5	1	Sink provision & size (• or ×)
				\	<	,	5	1	}	1	j	1	5	1	1	1	1	5	5		5	Grooves for door frames (< or ×)
				1	1	}	1				j	(}	1	1	1	1	1	1	(1	Balcony & terrace sill top finishing ¹⁰ (~ or ×)
				1	1		1	-	1	1	}	1	3	1	1))	f	ĵ	}	1	Screeding in bathroom & utility (v or x)
 			,	1		}	1	Barbar T	١	l	})	}	j	1	}	1	1			Screeding in 6" above FFL? (v or x)

Page 2 of 3

Quality Control Check Repot. Stage: After Plastering (Villas)

Overall quality of plastering? Plastering of compound wall & gate pillars (or x) Is plastering of compound wall and villa external walls 6" below FFL of setbacks? Plastering quality of parapet walls (or x)	☐ Good ☐ Avg. ☐ Bad Avg ☐ Yes ☐ No
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	√Yes □No
Plastering quality of parapet walls (✓ or ×)	ζ.
Plastering and finishing of chajjas (v or x)	
Remarks:	
	н