Quality Control Check Repot. Stage: After Plastering (Villas)

Villa No.	75	Stage		SI. No.	3233 \$
Company	AAH	Project	AVR Homes	Phase	
Prepared by	P. Si Kumer	Sign	Prod,	Date	11 2/18
Project Manager	50.00	Sign	Take	Date	11/12/18
Previous stage report no.	no.	8 6918	Report filed and signed by PM?	d by PM?	4Yes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Stop further work Proceed with furth Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required proceed with further work. ATR not required.	port to QC team. Procest submitting ATR on ing corrections pointedired.	eed only after recheck be QC report to QC team.	y QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance ¼". Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

	Ren	19	18	17	16	15	14	13	12	11	10	9	8	7	6	2	4	ω	2	-	S No
	Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/baleony 2	Terrace / balcony	Lobb y 2	1-AqqoT	Dining	Drawing	Toilet-4	Bedroom4	Toilet-3-	Bedroom-3	Toilet 2	Bedroom 2		Bedroom 1	Room
***************************************	115de 2		100				опу 2	eony 1				71 - P. C.				0.00	CT	KB	MT	MB	
tot	Morts		1	X	,	ς.	1			1	X	<	محتصيعه		1	e	V	ς.	5	<i>S</i>	Skirting Provision (• or ×)
totally	353		1	<	1	5	}	}	1)	1	<)))	}	<	ζ,	ς	ζ.	Finishing around door frame (• or ×)
bes	Com		1	<	1	<	}	1	})	<	<	1)	1	1		\	7	,	Beams & columns finishing (v or x)
1	produ		1	<	1)	}	}	I	5	İ	})	•	e e	1	1	*****	Finishing of lofts (v or x)
	الم الم		ļ	5	(<	ļ	})	J	\	ς)	7]	ŋ	<	<	<	7	Electrical junctions finishing (v or x)
	1		-	<	1	<)	Ì	1	}	<	5	,	}))	K	5	5	5	Window check (v or x)
	and		1	K	Вуссано	1	1	١	1	}	1	1	1	1	h)	X	1	5	1	Tiles provision
	helw		1	<	1	1	1	1)	}	1	J	1)))	<	1	5	1	Sink provision & size
_	2		-	<		<		•	}	1	١	ζ	1	1	1	1	<	<	5	5	Grooves for door frames (• or ×)
	towth		***	1	9	1	1	1	1	1	Ī	1	1)	,)	1	1	1	Ì	Balcony & terrace sill top finishing 10 (v or x)
	1.		1	1	1	(}	1	}	J	1	}	1)	1)	1	١	1	1	Screeding in bathroom & utility (• or ×)
	heder been		1	* THE COLUMN	1	1	1	7	1)	1]	1))	3	-	1)	}	Screeding in 6" above FFL? (• or ×)

Page 2 of 3

Quality Control Check Repot. Stage: After Plastering (Villas)

IVIISCEHANGOUS CHECK	
Overall quality of plastering?	☐ Good [VAvg. [] Bad
Plastering of compound wall & gate pillars (v or x)	
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?]Yes \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
Plastering quality of parapet walls (✓ or 🗙)	4
Plastering and finishing of chajjas (✓ or 🗙)	<
Remarks: . Compound wall and gate pillar's plasting	stering not done and
Set-backs, lavelline ust done	0