Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager Bode Muda	Prepared by S. Kulder	Company	Villa No. 4
on QC report to QC tear work after submitting / after making corrections not required.	MD Sign	31443	Bala runali Dianne Sign	sign	Project	Stage
m. Proceed only after rechect ATR on QC report to QC tear pointed out in the QC report		Report filed and signed by PM?	Shring	Supring.	Bloomdale	
k by QC. m. t. ATR not required.	For filling	ned by PM?	Date	Date	Phasc	Sl. No.
	☐ Yes ☐ No	√Yes □ No	S102/01/50	05/10/2018	· · · · · · · · · · · · · · · · · · ·	3)67)

Inspection should be done after:

- brickwork & 2 coats plastering is completed after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XX for major mistake that cannot be corrected.

 9"unplastered area from SFL should be left including in common areas and terraces.

 Windows must be checked with templates. Tolerance ¼".

 Provision of tiles in bathrooms, kitchen & wash areas (rough plastering).

 Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")

- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

	Kem	19	18	17	16	15	14	13	12	11	10	9	×	7	6	V	4	ω	2	-	S No
	Kemarks	Other	Utility	Kitchen	Portico	Head room	Terrace/ baleony-2	Terrace/balo	Lebby 2 Fun		Dining	Drawing	Toilet4	Bedroom 4	Toilet 3	Bedroom 3	Toilet 2	Bedroom 2	Toilet I	Bedroom I	Room
							ony-2	ony 1'	Family Work	Popi A					7.7	ري ين	7.8	St.K.	アル	むら	
				7		<]	ς.	<	4,	((1	1	<	ς.	7	۲	7	<	Skirting Provision (v or x)
				3	1	<	1	1	٠,	ζ	1	<	١	1	<	(<	ς.	7	ς.	Finishing around door frame (v or x)
				<	1	ς	1	\	7	ς	Ţ	ζ.	ŧ	-	ζ	ς	7	7	ζ.	<	Beams & columns finishing (v or x)
				J	י	1	,	1	J	J	1	١	1	*	١	1	1	1	1	(Finishing of lofts (v or x)
, and a second				\	1	1	1	١	(1	Ţ	ζ.	1	1	<	ζ	ζ	5	ς	5	Electrical junctions finishing (v or x)
				1	\	1	7	J	′	<	ſ	ζ.	1	i	<	ζ	۲	5	ς.	ζ	Window check (v or x)
			4	×	(1	1	1	Ţ	1	ſ	İ	1	ı	۲.	(<	1	<	1	Tiles provision (• or ×)
				1	1	1	J	1	,		[1		ļ	(j	1	1	ı)	Sink provision & size
				1	1	\	/	7	1	1	!	7	1	ı		ζ	ζ	5	١	5	Grooves for door frames (v or x)
				1	!		I	1	Ţ	1	١	\	!	1	(J	,	}	1	(Balcony & terrace sill top finishing 10(v or x)
				1	ſ	!	1	!	1	1	1	(7	1		(]	7		Screeding in bathroom & utility (v or x)
	£.			1	!	1	1	1	1	1	1	1	1	1		(7	,	5	1	Screeding in 6" above FFL? (v or x)

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	✓ Good Avg. Bad
Plastering of compound wall & gate pillars (v or x)	}
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Yes No
Diagraming and idea of sound 11.	
riastering quanty of parapet walls (or x)	
Flastering and finishing of chajjas (or x)	
Remarks	
Exciliding.	200