Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Stop further work. Proceed with further	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Villa No.
commendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after superforced with further work only after making a Proceed with further work. ATR not required.		10.	Rashenjan	P.Sci Kunar	Milgin estates	4-
eport to QC team. Proceed ter submitting ATR or sing corrections pointe ired.	MD Sign	エイスリー	Sign	Sign	Project	Stage
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.		Report filed and signed by PM?	Jah	Prety	Milan estate	
by QC. n. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	☐Yes ☐No	☐Yes ☐No	41/80/80	41/80/80	F)	27736

Inspection should be done after:

- brickwork & 2 coats plastering is completed after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

- T		<u>ــــر</u>	سرا				حا			Ι.,	1.0	T	7	_	(V)	Γ.	ļ	Γ		
Remarks	19 (18 1		16	15		13	-	-	_		L.	20	<u> </u>	_		<u> </u>	2		S No
ırks	Other	Utility	Kitchen	Portico	Head room	Terrace/-baleeny 2	Terrace /- balcony 1	Lobby 2	Lobby-1	Dining	Drawing	Toilet 4	Bedroom 4	Toilet-3	Bedroom 3	_	n 2	Toilet 1 Hr	Bedroom 1 MB	Room
	220		<	1	1	J)	})	<	×)	1	1)	<	ς,	<	<	Skirting Provision (✓ or ×)
			<u> </u>	J	1	1	1	1)	1	<	ī	})	}	<	5	<	~	Finishing around door frame (• or ×)
			<	1	1)	})]	<	~	į	•	1	J	<	<	5	\	Beams & columns finishing (▼ or X)
			<	}	1)	١	1	1	<	•	})	}	}	1	<	,)	7	Finishing of lofts (• or ×)
			メ]	})	J	}	}	<	<	1	١	1)	<	5	5	7	Electrical junctions finishing (v or ×)
			<	}	1	}	J)	-	<	<	1	7	1	}	/	ζ	<	<	Window check (✓ or ×)
			۲	}))	1	1	j	}	1	\	}))	X	١	<	1	Tiles provision (✓ or X)
			<	1	1)]	1	}	1	j	١	1	9	1	<	}	5	{	Sink provision & size (✓ or ×)
			<	j	1	})))	1	<	1	J	}	J	<	<	<	<	Grooves for door frames (• or ×)
			1	1	j	1	•		1	l	1	(١	١	1	1	J	}	1	Balcony & terrace sill top finishing ¹0(✓ or ×)
			1)	١)	J)	\		1	١	}	J	1	1)	l)	ſ	Screeding in bathroom & utility (or X)
			1	1	1	1	1)	1		1	1	1	į)	1	1	1)	Screeding in 6" above FFL? (or X)

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous cheek Overall mulity of plastering?	Good Avg. Bad
Plustering of compound wall & gate pillars (v or x)	`
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	✓Yes □No
Plastering quality of parapet walls (✓ or 🗙)	*
Plastering and finishing of chajjas (v or X)	7
Remarks:	