Recommendation: Checked By MD on Previous stage report no. Project Manager Prepared by Company Block No Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work. ATR not required. Ochomovadi Kyisha 3 オミユ なな MD Sign 30060 Sign Sign Project ł Report filed and signed by PM? Bloom dale For filling Date Phase Date Sl. No. Yes 22/5/18 2215118 303/1 Yes □ No L No

Quality Control Check Repot.

Stage: Before Casting Plinth Beam (Villas)

### Plinth Beam Check

#### Notes:

- Inspection should be done before casting of plinth beam.
- Prepare plinth beam Dimensions Check Plan as follows: Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark
- Show outer dimensions. (Tolerance 2")
- Show length and width of plinth beams (Tolerance 1")

- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

  Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Plinth Beam Dimensions Check Plan enclosed? \times Yes \sum No
insions Check Plan enclosed?

## Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

		Remarks:	Pedestal/column() self chart many in the pedestal/column() self chart many in	Column steel overlands and account to be made;	Level marking at 7' above FET is mode?	Brackets for elevation fortune:	A lignment of basing FIOVIGED?	Onality of Brosing Bersid 16	Have rode for the line, rod bending and concreting?	Quality of centering, rod bending and concreting.
		✓ Yes □ No	☐ Correct ☐ Needs correction	Yes No	□Yes □No □NA	☐Good MAvg. ☐Bad	☐Good ☑Avg. ☐Bad	□Yes □No №	Good VAvg. Bad	

### Plinth Beam Steel check.

- Mark v for correct or minor mistake which does not require correction
   Mark X for minor mistake that requires minor correction.
   Mark X for major mistake that requires correction by replacement or re-fixing.
   Mark X X for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

# Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)