2	Quality Control Check Repot.		Stage: Before Casting Plinth Beam (Villas)	nth Beam (Villas)	
Block No	44	1		SI. No.	30821
Company	SOV LLP	Project	Sol	Phase	X
Prepared by	V. Sanbeth	Sign	万工	Date	16-07-2018
Project Manager	porshottom	Sign		Date	8102-60-31
Previous stage report no.		28652	Report filed and signed by PM?	d by PM?	MYes □No
Checked By MD on	MD Sign	ign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	nit ATR on QC report to eed with work after subrick only after making cork. ATR not required	QC team. Pro mitting ATR or rrections points	ceed only after recheck by QC report to QC team.	by QC. ATR not required.	

Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam.
 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam Dimensions Check Plan as follows:

- Show outer dimensions. (Tolerance 2")
 Show length and width of plinth beams (Tolerance 1")
- c. Print an A3 size plan.

 Circle each coveret dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Deam Dimensions Check Plan enclosed?

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

	Vel	7	\top					<u> </u>	7			
	Nemarks:		7	6.	J.	א	4.	ŗ	,	ر	I.	SNo
		Expan and width of beams	Death and width of	Covering blocks for beams	Steel Check - Beams Bearing	St. 101 Section Decision of Change of Change	Steel Check - Reams Overlanding of Carti	Steel Check - Beams Extra Bars	Sicci Clieck - Beam Size of bars	Stool Charles Down In College	Steel Check - Beam no of rode	Item
			1	>		<u> </u>				4	(v or x)	Quantitative Check
		Good Avg. Bad	LY Good Avg. Bad		Good Avg. Bad	☐ Good ☐ Avg. ☐ Bad	[]	Good LAvo Rad	Good Avg. Bad	Good ☐ Avg. ☐ Bad	(Good / Avg. / Bad)	Qualitative Check

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	ယ	2.		S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	The state of the s	Ż.		<u> </u>	✓		4	Quantitative Check
	☑ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Good Avg. Bad	Good ☐ Avg. ☐ Bad	Good ☐ Avg. ☐ Bad	Qualitative Check / (Good / Avg. / Bad)