Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making of the proceed with further work. ATR not required	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
commendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck I Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.		98198	Slewan Klynns	S. Sund Klynos	323 () (P)	48
C team. Proditting ATR of	MD Sign		Sign	Sign	Project	
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.		Report filed and signed by PM?	June of	3	AGH GWMotas	
QC.	For filling	PM?	Date	Date	Phase	SI. No.
	☐ Yes ☐ No	☐Yes ☐ No	36/10/17	26/10/17	ĵ	26296

Plinth Beam Check. Notes:

- Inspection should be done before casting of plinth beam.

 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam Dimensions Check Plan as follows:

 a. Show outer dimensions. (Tolerance 2")

 b. Show length and width of plinth beams (Tolerance 1")

 c. Print an A3 size plan.

 Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Plinth Beam Dimensions Check Plan enclosed?	
☐Yes ☐No	

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	Good Avg. Bad
Have rods for staircase slab been provided?	□Yes □No
Quality of Bracing Provided?	☐Good ☐Avg. ☐Bad
Alignment of beams on outer side?	☐Good ☐ Avg. ☐ Bad
Brackets for elevation features provided?	□Yes □No □NA
Level marking at 2' above FFL is made?	□Yes □No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	☐Correct ☐ Needs correction
Remarks:	
	77 78 88 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8

Plinth Beam Steel check.

Notes:

- Mark for correct or minor mistake which does not require correction
 Mark × for minor mistake that requires minor correction.
 Mark × for major mistake that requires correction by replacement or re-fixing.
 Mark × x for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	3.	2.	1.	S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
TO THE PROPERTY OF THE PROPERT	5	<	5	,	5	ς.	ς	Quantitative Check (\(\sigma \) or \(\times \)
TOTAL TRANSPORT	☐ Good ☑ Avg. ☐ Bad	Good Avg. Bad	Good Avg. Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Good Avg. Bad	Good ☐ Avg. ☐ Bad	Qualitative Check (Good / Avg. / Bad)

•