\simeq
2
15
10
=
intra
9
Œ
IÇ.
~
E
12
-
1
ţ
-0
15
=
Œ
1
5
Ħ
J
12
12
2
=
5
Œ
22
2

Recommendation: Slop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager K.		Company	Villa No.
mit ATR on QC re seed with work aft ork only after mak ork. ATR not requ			K. Purshotham	G. RAJESH	SOV (LLP)	8 h
port to QC team. Procer submitting ATR on ing corrections pointedired.	MD Sign	33204	Sign	Sign	Project	Stage
ced only after recheck of QC report to QC team out in the QC report.		Report filed and signed by PM?	-A	E M	Sov	il a
by QC. ATR not required.	For filling	d by PM?	Date	Date	Phase	SI. No.
	☐ Yes ☐ No	√Yes □No	11/06/2019	11/00/2019	र्द्ध रे	33770

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance ¼".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	19	18	17	16	15	14	13	12		10	9	∞	7	6	S	4	w	2	<u></u>	S No	
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/ balcony 2	Terrace/balcony 1	Lobby 2	Lebby-1	Dining	Drawing	Forlet 4"	Bedroom 4	Toilet 3-	ယ်		Bedroom 2 K. 段		Bedroom 1 M.B	 	
			<	1	5	1		}]	<	5	1	1	1]	1	<	, ļ	5	Skirting Provision (v or x)	
	-		<	1	5	*	1	1	}	4	7	Ŋ	}	1	†	\	<	<	7	Finishing around door frame (• or ×)	
	_		<	1	<	5	١	1	1	<	7		1	\		<	<	<	<	Beams & columns finishing (v or x)	
			<)	l	1	1	1	1	ţ	1	1	1	Ì	1	1	1	1	ነ	Finishing of lofts (• or ×)	
			<	1	<	<	١	1	1	<	7	1]	1	1	5	7	7	ζ.	Electrical junctions finishing (v or x)	
			< \	1	<	5	1))	<	5	g - mac	})		<	5	<	5	Window check (• or ×)	
		,		1)	1	1	1	3	1	1	,	j	1	1	<	1	<	1	Tiles provision (• or ×)	
		-		,	1	1	1))	1	1	•)	}		١	1	•	١	Sink provision & size	
		,	<	1	<	*	1	1]	1	1	1)	Agran in			<	< '		Grooves for door frames (✓ or 🗙)	
				1	,		1	١)	1	١	1	· ·]	1)		1	1	Balcony & terrace sill top finishing 10 (v or x)	
			1	!] •		1]]	١)	Armina.	-	1	}	١	١	١	١	Screeding in bathroom & utility (or x)	
			1		1		1	١		1	١	1		F		1	1	1		Screeding in 6" above FFL? (v or x)	

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check Overall quality of plastering? Plastering of compound wall & gate pillars (v or x)	☐ Good ☐ Avg. ☐ Bad
Flastering of compound wall & gate pillars (or X)	,
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	✓Yes □ No
Plastering quality of parapet walls (v or x)	5
Plastering and finishing of chajjas (✓ or 🗙)	<
Remarks:	