Block No 49 Company Sov(LLP) Project Prepared by Project Manager Project Manager Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work only after making corrections pointed out in the QC report. ATR not required.	į į	Quality Control Check Repot.		Stage: Before Casting Plinth Beam (Villas)	nth Beam (Villas)	
Project Sign Sign Sign Phase Date 30710 Report filed and signed by PM? Sign To QC team. Proceed only after recheck by QC. ubmitting ATR on QC report to QC team. corrections pointed out in the QC report. ATR not required.	Block No	49	ī,		SI. No.	32335
Sign Sign Date 30710 Report filed and signed by PM? Sign To QC team. Proceed only after recheck by QC. ubmitting ATR on QC report to QC team. corrections pointed out in the QC report. ATR not required.	Company		Project	500	Phase	
Sign Sign Report filed and signed by PM? Sign Report filed and signed by PM? For filling to QC team. Proceed only after recheck by QC. ubmitting ATR on QC report to QC team. corrections pointed out in the QC report. ATR not required.	Prepared by	くられる大	Sign		Date	
Sign Report filed and signed by PM? Sign For filling to QC team. Proceed only after recheck by QC. ubmitting ATR on QC report to QC team. corrections pointed out in the QC report. ATR not required.	Project Manager	3	Sign		Date	11.7.18
Sign For filling to QC team. Proceed only after recheck by QC. ubmitting ATR on QC report to QC team. corrections pointed out in the QC report, ATR not required.	Previous stage report no.		30710	Report filed and signe	d by PM?	Yes No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	MDS	ign		For filling	☐Yes ☐No
rroceed with further work. ATR not required.	Recommendation: Stop further work. Submi Stop further work. Proce Proceed with further work Proceed with further work	it ATR on QC report to sed with work after subt k only after making cor k. ATR not required.	QC team. Pro nitting ATR o rections point	ceed only after recheck b n QC report to QC team. od out in the QC report. /	y QC. ATR not required.	

Quality Control Check Repot.

Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam.
 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam Dimensions Check Plan as follows:

 a. Show outer dimensions. (Tolerance 2")
 b. Show length and width of plinth beams (Tolerance 1")
 c. Print an A3 size plan.
 Circle each correct dimension with green colour. Circle each incorrect dimension with green colour. Circle each incorrect dimension with green colour. Circle each incorrect dimension with green colour. Or self check report similar to report for column check. QC must collect report and attach the same to this report.

	Plinth Beam Dimensions Check Plan	
-	enclosed? Yes No	
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good [Avg. ☐ Bad
Have rods for staircase slab been provided?	✓Yes □No
Quality of Bracing Provided?	☐ Good [☐ Avg. ☐ Bad
Alignment of beams on outer side?	Good ☐ Avg. ☐ Bad
Brackets for elevation features provided?	☐ Yes ☐ No ☑NA
Level marking at 2' above FFL is made?	√Yes □No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	☐ Correct ☐ Needs correction
Pedestal/column0 – self check report attached?	√Yes □No
Remarks:	
	1

Plinth Beam Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.

 Mark X X for major mistake that cannot be corrected.

 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7. I	6.	5. S	4. S	3.	2. S	1. S	S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	<	<	•	(4	×	<	Quantitative Check (• or ×)
	Good Avg. Bad	☐ Good ✓ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Good Avg. Bad	☑ Good ☐ Avg. ☐ Bad	Good Avg. Bad	Qualitative Check (Good / Avg. / Bad)