	Quality Control Check Report.
•	Stage: After of
	Stage: After Column Casting

Diaglanta *		2			
BIOCK NO.	<i>5</i> /00	Column No.	<u>0</u>	SI. No.	34414
Company	155	Project	AVR Silknown	Phase	)
Prepared by	0.00000	Sign		Date	00000
Project Manager	CAT LOSON	Sign	1	Date	900
Previous stage report no.		72175	Report filed and signed by PM?	d by PM?	Yes No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation:  Stop further work  Stop further work  Proceed with furt  Proceed with furt	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Proceer submitting ATR on ing corrections pointed ired.	sed only after recheck b QC report to QC team. I out in the QC report. A	y QC.	
Columns Position Charle					

## Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab. Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.

Slah Dimensions Check	Columns Position Check Plan enclosed?	. Circle each correct dimension with green colour. Circle each in
	Yes No	h incorrect dimension with red colour and mention actual dimension next to it

## DITTETISIONS CHECK.

Notes:

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:

  a. Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.

	Specified thickness of slab?	Siao Dilhensions Check Pian enclosed?	Slat Dimeni	2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention ac
NA	Actual thickness of slab?	Yes No	a constant what fed colour and inclinion actual difficultion flext to It.	resof dimension with rad colour and mention portfol dimension posts is

1		Qualit
nding and amounting	ij	y Control (
}		Check Repo
0	••	t. Stag
		e: After C
	100 00000	olumn Ca
-		Quality Control Check Repot. Stage: After Column Casting (villas)

		Remarks:
Bad	Good Avg.	Quality of infrastructure for curing.
	Yes No	Is the pressure in the curing pipe more than 15' head?
a James.	20	Frequency of curing in number of times a day (enquire from labourers)
	189	Distance of tap from furthest distance that requires curing. (max permitted 100')
	∵Yes □No	Gunny bags used for column curing?
	☐Yes ☐No	Drum (200 lts) provided for curing?
	☐ Yes ☐ No	
	☐ Yes ☐ No	Bunds for curing made on slab?
		Curing.
		Remarks:
√Yes  No		Have 6 cubes each for columns and slab casted and numbered for testing?
egir 1 <sub>3</sub>	e than 1"	Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"
Good Avg. Bad	875.c.	Are the honey combs is slab and columns packed?
☐ High ☐ Medium. ☐ Low		Number and size of honey combs?
☐ Good ☑ Avg. ☐ Bad		Quality of starters?
Good Avg. Bad		Quality of centering, rod bending and concreting?
	4	Quality of centering, rod bending and concreting.

## Quality Control Check Repot. Stage: After Column Casting (villas)

## Columns height, plumb, steel & level marking check.

Notes:

- Mark  $\checkmark$  for correct or minor mistake which does not require correction Mark  $\times$  for minor mistake that requires minor correction.

  Mark  $\times$  for major mistake that requires correction by replacement or re-fixing. Mark  $\times$   $\times$  for major mistake that cannot be corrected.

  Tolerance: Plumb 0.25".

Circle actual height of columns if level differs from specified height by more than 1".

20.	19.	18.	17.	16.	15.	14.	13.	12.	==	10.	, ,	8.	7.	6.	5.	4.	· ω	2.	-			S No
								£15	99	65	E.A.	T	O, .	CX.	()	500	Fi.	T	7		8	Col No.
								Ca	Co Co	C G	Ca			C3	0	Ca	G	G	Q		, <del></del>	Col type
								87	716	0.0	1	9-17	2/1/2	5.472	8. AIL	S. TE	9, A7,	5 410	8.47		Spec.	Heigl
							(	Ø.↑	6.	5		(P)	(S)		8,00				, A, OC		Actual	Height in ft
-								ζ	ς	ζ.	7	<	(	(	ς	(	ς.	ς.	ς	rods	No of	Steel (
								ς.	<	(	(	<	(	(	(	(	ζ	ς	(	rods	Size of	Steel ( v or x)
								ς	(-	ς	<b>\</b>	(	(	۲	(	(	<	<b>(</b> ·	<			Honeycombs
								ζ.	(	٢	(	(	(	(	(	(	(	ζ.	(		Side 1	Plumb
								(	(	(	(	(	<	(	ς	ς	ζ	(	(		Side 2	Plumb ( • or ×)
☐Yes ☐No	☐ Yes ☐ No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	column?	marked on	Reference level						