Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Villa No.
omit ATR on QC rej oceed with work aft vork only after maki vork. ATR not requi			Rodonwroth Knishna Sign	Pisi kuns	127	22 12
port to QC team. Pro er submitting ATR o ing corrections point red.	MD Sign	32687	Sign	Sign	Project	Stage
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck learn. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.		Report filed and signed by PM?	- Novey	からから	Bloomdale	
by QC. n. . ATR not required.	For filling	d by PM?	Date	Date	Phase	SI. No.
	☐ Yes ☐ No	∑Yes □No	11/3/19	11/2/11	1	33126

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

- Mark for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark X X for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major paistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")

- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

	Ren	19	18	17	16	15	14	13	12		10	9	∞	7	6	S	4	ယ	2	1	S No
Told Y H	Remarks CV . Skivh	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony-2	Terrace / balcony 1	Lobby 2	Lobby I f. borge	Dining	Drawing		Bedroom 4 Progarum	Toilet 3 KT	Bedroom 3 1-3		n 2	_	Bedroom 1 GB	Room
Master	<del>5.</del> 5		(	<	ς.	<	1	<	1	<	ζ	<	ſ	久	<	<	5	<	<	5	Skirting Provision ( • or ×)
を	provision		1	<	ς	<	١	<	1	{	J	ζ	1	<	<	Κ.	7	7	7	<	Finishing around door frame ( v or x)
			-	<	ζ	<	ſ	<	1	<	<	<	1	<	ς	<	5	<u> </u>	<		Beams & columns finishing ( • or ×)
Screedis	704		1	<	(	9	}	1	1	١	1	J	1	١	J	}	J	ļ	J	J	Finishing of lofts ( • or ×)
ζ 3	providue		}	<	<	<	1	<	ſ	<	<	ς	1.	\	<	5	ς	¥.	ς.	5	Electrical junctions finishing ( • or ×)
Ť	3		1	<	ĵ	<	-	[	1	<	<	<	1	۲	(	ς.	7	7	5	7	Window check (✓ or 🗙)
fore	700		1	<	<	Í	١	<	1	1	١	)	l		<	J	<	j	5	J	Tiles provision (✓ or 🗙)
adough	a Your		1	<	1	(	J	١	1	ļ	1	١	1	5	<	ſ	<	l	<	1	Sink provision & size (✓ or 🗙)
۲	3		1	<	,	<	1	<	•	1	I	ζ.	-	<	5	<	ς (		5	5	Grooves for door frames ( v or x)
			1	١	j	ļ	]	<	1	ţ	1	1	1	1	J	J	1	5	5	1	Balcony & terrace sill top finishing 10 ( v or x)
			)	1	1	1	1	{	1	ţ	ſ	9	1	}	<	1	X.	1	ţ	]	Screeding in bathroom & utility ( • or ×)
				١	١	١	1	1	1	ļ		)	1	1	۲	1	<	\	ſ	}	Screeding in 6" above FFL? ( v or x)

## Quality Control Check Repot. Stage: After Plastering (Villas)

TATISCELIBILEOUS CHECK	
Overall quality of plastering?	Good Navg. Bad
Plastering of compound wall & gate pillars ( v or x)	<
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	ZYes □ No
Plastering quality of parapet walls ( v or x)	
Plastering and finishing of chajjas (✓ or 🗙)	
Remarks:	