Block No.	53	Column No.	10	SI. No.	32879
Company	SOY/LLP)	Project	SOV :	Phase	( <u>~</u> )
Prepared by		Sign	Sonders	Date	12/20/21
Project Manager	R. Rushotham	Sign		Date	12/02/19
Previous stage report no.	0.	32165	Report filed and signed by PM?	d by PM?	Yes No
Checked By MD on		MD Sign		For filling	□Yes □No
Recommendation:  Stop further work. Submit ATR on QC report  Stop further work. Proceed with work after su  Proceed with further work only after making of the proceed with further work. ATR not required.	Submit ATR on QC re Proceed with work aft r work only after maker work. ATR not requi	port to QC tcam. Proceer submitting ATR on ing corrections pointedired.	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	y QC. ATR not required.	
Columns Docition Chast	7		•		

Quality Control Check Repot.

Stage: After Column Casting (villas)

## Columns Position Check.

#### Notes:

- Inspection should be done after easting of columns at each stage and before starting centering works for each slab.
- Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- d.c Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.

CONTRACTOR CONTRACTOR CONTRACTOR AND
√Yes □ No

### Slab Dimensions Check.

#### Notes:

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- Show location of sunken slab. Show inner dimensions of ducts and lift well. (Tolerance 1")
- Print an A3 size plan.

Specified thickness of slab?	Slab Dimensions Check Plan enclosed?	2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention a
Actual thickness of slab?	□Yes □No N.A	ension with red colour and mention actual dimension i
		next to it,

# Quality of centering, rod bending and concreting

Quality of centering, rod bending and concreting?	
Quality of starters?	L Good Mayg. Bad
Number and size of honey combe?	☐ Good Avg. ☐ Bad
Are the honey combass.	☐ High ☐ Medium. ☐ Low
in none'y collies is slab and columns packed?	☐Good ☐ Avg. ☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"	
Have 6 cubes each for columns and slab casted and numbered for testing?	TVec No
Remarks:	100
Curing.	
Bunds for curing made on slab?	
-	K. 1
Drum (200 lts) provided for curing?	
	-
Frequency of chiring in number of times and requires curing, (max permitted 100') $20^{1}-0^{11}$	
2 times a day (enquire from labourers)	
ore than 15' head?	
Quality of intrastructure for curing.	Bad
Kemarks:	

## Quality Control Check Repot. Stage: After Column Casting (villas)

# Columns height, plumb, steel & level marking check.

- Mark \( \sqrt{ for correct or minor mistake which does not require correction Mark \( \times \) for minor mistake that requires minor correction. Mark \( \times \) for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected. Tolerance: Plumb 0.25".

Circle actual height of columns if level differs from specified height by more than 1".

stew			
	( ( ( ( ( .	( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( (	( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( (
(	( ( ( ( ( (	( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( (	( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( (
666	< < < <.	< < < < < < <	< < < < < < < < < < < < < < < < < < < <
☐Yes ☐No ☐Yes ☐No ☐Yes ☐No ☐Yes ☐No	Yes I		☐ Yes ☐ No