Stop further work. Submit ATR on (A) report Stop further work. Proceed with work after superfection of the proceed with further work only after making of the proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.			Dranged h.	Company	Riock No
Stop further work. Submit ATR on (X) report to QC team. Proceed only after recheck I Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	MD Sign		Zakir Hussain Sign	G. RAJESH Sign	AUM	54	Quality Control Check Repot.
Stop further work. Submit ATR on (AC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	For filling	Report filed and signed by PM?	Date	LANC Date	AVR CIVINGLOY Phase	Sl. No.	Stage: Before Casting Plinth Beam (Villas)
equired.	ng Yes No	2 LYes \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	28/09/19	28/09/19	1	34472	n (Villas)

Quality Control Check Repot.

Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam
 Yellow enamel paint to be used for marking FFL of flowing. Mark 2° above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2.4" (in case of RCC slab) below the mark.
 Prepare plinth beam. Dimensions Check Plan as follows:

 Show outer dimensions. (Tolerance 2")
 Show length and width of plinth beams (Tolerance 1")
 Print an A3 size plan.

- Circle each correct dimension with green colout. Circle each incorrect dimension with red colour and mention actual dimension-next to it.

 Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Plinth Beam Dimensions Check Plan enclosed?	3
☑Yes □No	and the first of the second se
	o disacher.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

sunt tour sold sold not be soldied by the
Remarks: Shall Shall have the shall
Pedestal/column0 – self check report attached?
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)
Level marking at 2° above FFL is made?
Brackets for elevation features provided? No NA
Alignment of beams on outer side." Good Avg. Bad
Quality of Bracing Provided?
Have rods for staircase slab been provided?
Cuality of centering, rod bending and concreting?
Quality of centering, rod bending and concreting.

Plinth Beam Steel check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction Mark X for minor mistake that requires minor correction.

 Mark X X for major mistake that requires correction by replacement or re-fixing. Mark X X for major mistake that cannot be corrected.

 ('olumns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	3.	2.	-	s No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	V	ζ.	(~	V	and a second	Quantitative Check
	Good Avg. Bad	☐ Good ☑ Avg. ☐ Bad	Good Avg. Bad	☐ Good [Avg. ☐ Bad	Good V Avg. Bad	Good Avg. Bad	Good Avg. Bad	Qualitative Check (Good / Avg. / Bad)