	Quality Control Check Repot.		Stage: Before Casting Plinth Beam (Villas)	Beam (Villas)	2	4.6
Block No	74 -			SI. No.	98813.	
Company	120 () 10	Project	ノラナ	Phase		
	ANC LECT	Sign		Date	20/2/27	
Prepared by	M. Sin kunn	Sign		Data	29 121 13	
Project Manager	M. Suzesh.	Sign		Date	2911117	_ 1
Previous stage report no.	55 W.O.C.		Report filed and signed by Five	••		1
Checked By MD on	0.0501	MD Sign		For filling	☐Yes ☐No	868
Checked by mb on						00. 0
Recommendation:  Stop further work. Sul Stop further work. Pro Proceed with further v	commendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck be Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. A proceed with further work only after making corrections pointed out in the QC report.	QC team. Pro mitting ATR o rections point	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	)C. R not required.		1
Proceed with further work. ATR not required.	vork. ATR not required.					- 1

## Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam.

  Inspection should be done before casting of plinth beam.

  Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark.

  Prepare plinth beam Dimensions Check Plan as follows:

  a. Show outer dimensions. (Tolerance 2")

  b. Show length and width of plinth beams (Tolerance 1")

  c. Print an A3 size plan.

  c. Print an A3 size plan.

  Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Plinth Beam Dimensions Check Plan enclosed?	
Plan enclosed?	
Yes No	

## Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

## Plinth Beam Steel check.

- Mark v for correct or minor mistake which does not require correction Mark x for minor mistake that requires minor correction.

  Mark x for major mistake that requires correction by replacement or re-fixing.

  Mark x x for major mistake that cannot be corrected.

  Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

•	Remarks	7.	6.	5.	4.	3.	2.	-	S No
		Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	# Item
		<	\ \ .	V	<	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	<	<	Quantitative Check  * ( • or X)
		√Good Avg. L Bad	Good Avg. Bad	Good Avg. Bau	A COOUL DAY	Good Ave Bad	V Good Avg. Dad	Good Avg. Dad	Qualitative Check (Good / Avg. / Bad)