r
Duality
Quality Control Check Repot.
Check b
Repot.
Stage: Before Casting Slab (\)
Before
Casting
Slab (
Villas)

Company Com	71 - 17					
Scy CLLP) Project Sign Sign Date Sign A Report filed and signed by PM? Date Date MD Sign MD Sign MD Sign MD Sign Proceed only after recheck by QC. roceed with work after submitting ATR on QC report to QC team. work only after making corrections pointed out in the QC report. ATR not required. Work, ATR not required.	Block No	. 58	Slab No.	0	SI. No.	71692
Sign Sign Date Sign One had be and signed by PM? Date 31618 Report filed and signed by PM? Date MD Sign MD Sign MD Sign For filling For filling work only after submitting ATR on QC report to QC team. work only after making corrections pointed out in the QC report. ATR not required. work, ATR not required.	Company	Sev CLLP)	Project	5°4	Phase	X
Sign Sign Date 31618 Report filed and signed by PM? MD Sign MD Sign MD Sign For filling For filling work only after submitting ATR on QC report to QC team. work only after making corrections pointed out in the QC report. ATR not required. work, ATR not required.	Prepared by	4 Sankot	Sign	人人人人人	Date	29/10/10
Burney 21618 Report filed and signed by PM? MD Sign For filling work only after submitting ATR on QC report to QC team. Proceed only after recheck by QC. rock only after making corrections pointed out in the QC report. ATR not required. work. ATR not required.	Project Manager	Purshattam	Sign		Date	09-10-18
MD Sign For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Previous stage report	no.	31618	Report filed and signed by PN	1?	☑Yes ☐No
ork. Submit ATR on QC report to QC team. Proceed only after recheck by Q ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR urther work. ATR not required.	Checked By MD on		MD Sign		For filling	☐Yes ☐No
	Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Submit ATR on QC report to Proceed with work after submer work only after making conter work. ATR not required.	QC team. Pr mitting ATR rrections poir	oceed only after recheck by QO on QC report to QC team. ted out in the QC report. ATR	not required.	

Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting. Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- Show inner dimensions of ducts. (Tolerance 1") Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension

Slab Dimensions Check Plan enclosed?			√Yes □No	No		10.10
Staircase - mid landing1	pecified ht:	4.5"	Actual ht:	4-51.4	Specified ht: 4.5" Actual ht: 4.5" Within tolerance of 1/2"?	√Yes □No
Staircase - mid landing 2	Specified ht:]	Actual ht:]	Within tolerance of 1/2"? Yes No	Yes No
	Specified wd: 620/2 Actual wd: 621"	5-01/2"	Actual wd:	6-111	Within tolerance of 1/2"?	✓ Yes □ No
Staircase slab thickness S	Specified:	57	Actual:	4,	Within tolerance of 1/2"?	✓ Yes □ No

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Notes: Slab Steel check.

Mark o for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark X for major mistake that requires correction by replacement or re-fixing.
 Mark X X for major mistake that cannot be corrected.
 Cohumns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

てののかで、十七十十七十万万人、メンノノー