Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
t ATR on QC report to ed with work after subset only after making core. ATR not required.	MD Sign	31625	K. Puntothem	P. Sai Kunar	SOY(LLP)	39
QC team. Proc nitting ATR on rections pointed	ign		Sign	Sign	Project	
eed only after recheck QC report to QC team I out in the QC report.		Report filed and signed by PM?	K	Righ	No 5.	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	☐ Yes ☐ No	IJYes □No	21/12/18	24/12/18	Ā	32460

Quality Control Check Repot.

Stage: Before Casting Plinth Beam (Villas)

Plinth Beam Check. Notes:

- Inspection should be done before casting of plinth beam.

 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam Dimensions Check Plan as follows:

 a. Show outer dimensions. (Tolerance 2")

 b. Show length and width of plinth beams (Tolerance 1")

 c. Print an A3 size plan.
- 4 10
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Lillian Death Differsions Check Flan enclosed?		es
	CHECK I lan eliciosed?	
Jimension		

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

ng?	Good Avg. Bad Yes No Good Avg. Bad Good Avg. Bad Yes No NA Yes No NA Ves No
	Correct Needs correction
Pedestal/column0 – self check report attached?	√Yes □No
Remarks:	
	The state of the s

Plinth Beam Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.
- Columns overlapping length should be 45 to 50 D.

:

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)