Quality Control Check Repot. Stage: After Plastering (Villas)

VIIIa No.		Stage		S No	
	65	Sun G		SI. INO.	32078
Company	AGH	Project	AVE Company	Phase	
Prepared by	S. Kuldey	Sign	Supply	Date	In   10
Project Manager	zakir ubssain Sign	Sign	3	Date	15/2/10
Previous stage report no.		31536	Report filed and signed by PM?	d by PM?	Yes No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	mit ATR on QC receed with work aftork only after making.  ATR not require	port to QC team. Proceer submitting ATR on ing corrections pointed red.	eed only after recheck be QC report to QC team. I out in the QC report.	y QC. \TR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark **XX** for major mistake that requires correction by replacement or re-fixing. Mark **XXX** for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance ½".

  Provision of tiles in bathrooms, kitchen & wash areas (rough plastering).

  Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")

- 8. Check size of sink bowl. Hole snowled to a measurement of sill doors frames should have 1/2" grooves.

  9. All doors frames should have 1/2" grooves.

  10. Sill top must be of uniform thickness, correct height, at one level & without broken edges.

	Rem	19	18	17	16	15	14	13	12		10	9	0	7	6	S	4		2	1-	S No
	Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/1		Lobby 2	Lebby-1	Dining	Drawing	Toilet-4	Bedroom-4	Toilet 3	Bedroom 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom	Room
						B	balcony 2	balcony 1	1	Rooja				14				12 KB	3:1	n 1 3.53	
				<	-	>	•	1	1	(	1	1	1	1	1	ſ	(	7	7	1	Skirting Provision ( • or ×)
				1	1	1	ı	1	1	1	1	(	(		1	1	(	<	(	(	Finishing around door frame ( • or ×)
				7	1	(	1	1	1	1	1		1	١	1	f	5	<	7	1	Beams & columns finishing (v or x)
		-		7	1	1	1	1	1	!	1	1	1	1	1	1	(	1	!	1	Finishing of lofts ( • or ×)
-			(		1	(	1	1	1	(	1		1	1	1 1	-		5	,		Electrical junctions finishing ( v or x)
			1	1	1		1		1		1			1 1	1	(	, ,	,	,		Window check (✓ or X)
			7			1 1		1 1			1 1			1	1 1		7	15	1		Tiles provision  ( v or x)
		-	×	(		!	1 1						1	1	1	1		,	1		Sink provision & size
		_	1	1 1	(	\	1 1	1		1	1	١		!	1 1	<	1	. 5	1		Grooves for door frames (✓ or 🗙)
	-		1		1			1	1	1	1	1	1	1	)	1	1	1	1	1	Balcony & terrace sill top finishing 10 ( v or x)
25			1	1	1	1	1	1	1	1	١	1	1	1		1	1	1	1		Screeding in bathroom & utility ( or x)
			1	1	1	1	1	1	1	-	1	1	1	1	1	ı	1	1		S	Screeding in 6" above FFL? (v or x)

## Quality Control Check Repot. Stage: After Plastering (Villas)

)	Z
	Miscellaneous
=	llan
:	eou
	s ch
1	check
1	

specified height.	remarks: NoTE: set have fravilla not levelled asper
7	and
7	Plantage and E. 1
Yes No	Diodoring on Compound wan and villa external walls 6" below FFL of setbacks?
×	Is platfering of compound wan & gate pillars ( v or x)
☐ Good ☑ Avg. ☐ Bad	Overall quality of plastering?