1
Quality
Quality Control Check Repot. Stag
Check Repot.
Repot.
Stage:
Stage: Before Casting Plinth Beam (Villas)
Casting
Plinth]
Beam (
Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. A Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
it ATR on QC report to sed with work after subn k only after making cor k. ATR not required.	MD Sign	29133	Balanneti Korhan	D. Six Kumen Sign	KNM	+2
QC team. Proce nitting ATR on or rections pointed	gn		Sign		Project	
ed only after recheck QC report to QC team out in the QC report.		Report filed and signed by PM?	A CONTRACTOR	Redo	Roundonte	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	LyYes No	23/3/18	23/3/18	Ì	29770

Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam.

 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam. Dimensions Check Plan as follows:

 a. Show outer dimensions. (Tolerance 2")

 b. Show length and width of plinth beams (Tolerance 1")

 c. Print an A3 size plan.

4 10

- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and montion actual dimension next to it.

 Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

5		
	linth Beam Dimensions Check Plan enclosed?	
	4.	
	\\\\Yes	`
	□ No	
	ŗ	
30	•	

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

□ Good □ Avg. □ Bad □ Yes □ No □ Good □ Avg. □ Bad □ Yes □ No □ YNA □ Yes □ No □ Vorrect □ Needs correction □ Yes □ No
--

Plinth Beam Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark X for major mistake that requires correction by replacement or re-fixing.
 Mark X X for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	, no.	" "		•=-	S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Heel Check - Beam no of rods	Item
	<	5	<	<		<	<	Quantitative Check
	Good Avg. Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	√Good Avg. Bad	Good Avg. Bad	✓ Good ☐ Avg. ☐ Bad	✓ Good Avg. Bad	Qualitative Check (Good / Avg. / Bad)