Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Stop further work Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Villa No.
scommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making Proceed with further work. ATR not required		no.	Rundharm	J-Sanketh	Sov(LLP) Project	1 78
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	MD Sign	34154	Sign	Sign	Project	Stage
eed only after recheck l QC report to QC team I out in the QC report.		Report filed and signed by PM?	Ve	V- Swhigh	Sor	
by QC. ATR not required.	For filling		Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	Yès No	16 09 19	16/09/19	X	34381

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be I" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Remarks	19	18	-	+			-			10	9	8	7	6	5	4	ω	2	-	S No
arks	Other	Utility	Kitchen	Portico	Head room	-l'errace/ balc		Lobby 2	Lobby 1	Dining	Drawing	Toilet-4	Bedroom 4	Toilet 3	Bedroom 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom 1	Room
						balcony 2	balcony 1									不	KT.	オ	35	
			1	T. Jake	<		gradua (*****		<u> </u>	<u> </u>	, ,	(1	1	20.1.28	<,	Especial Control	<	Skirting Provision (v or x)
			<u>-</u>		<>	!	1	-	1		<i>\</i>			ĵ	1	<	ζ,	۲,	<,	Finishing around door frame (v or x)
		k	`\	<	<,		\	1	1	<	<,	* - TET- 100	2	1.51	4	<	ζ,	<.		Beams & columns finishing (v or x)
			5				£			6.79		1		i	t-mar		:	a -	a_ 00	Finishing of lofts
		<		ζ,	ζ.	į	ì	ì)		<,	8	27.4	,				<, <	, /	Electrical junctions finishing (v or x)
		4				Blan carried	9-7	i comercia	1	<.				Production of the Contract of				*		Window check
		K			50,	7		1		E-year.	Ì	A. C. C.	e	,	K	,				Tiles provision (or ×)
		7				Ī		***					100	100			-	Linco		Sink provision & size (or x)
		<				A	*	\			1	C. C.	-		<		<<			Grooves for door frames (< or ×)
		-			1		Carre		· [ĵ	t law			1 1		(I	Balcony & terrace sill top finishing 10 (or x)
				Specific	in the second	B 110	\		4	1	Įį.	1	T-response	ì	C.	12/14		EL.	5	Screeding in bathroom & utility (v or x)
		1		· screen				Ì		V	1		1	1		1 0	4.11		S	Screeding in 6" above FFL? (v or x)

Quality Control Check Repot. Stage: After Plastering (Villas)

INTISCEITAITEOUS CHECK	
Overall quality of plastering?	Good Avg. Bad
Plastering of compound wall & gate pillars (• or ×)	
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Yes No
Plastering quality of parapet walls (• or *)	
Plastering and finishing of chajjas (v or x)	
Remarks: 6" below Frl of cettacks plastoning no	t deric at South
Side of Willa External walls.	