Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Stop further work Proceed with furth	Checked By MD on	Previous singe report no.	Project Manager	Prepured by	Compuny	Villa No.
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.		no.	Plate Salt 8	May Ga hiller	Milyn, est-to, Project	\$c D
eport to QC team. Proc fter submitting ATR or king corrections pointe pired.	MD Sign	29382	Sign	Sign	Project	Stage
ced only after recheck a QC report to QC team d out in the QC report.		Report filed and signed by	M. war	f the	Milgin estate Phase	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	□Yes □No	⊠Yes □No	28/03/18	22/03/18	H	29762

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check,

- Mark v for correct or minor mistake which does not require correction

- Mark X for minor mintake that requires minor correction.

 Mark XX for major mintake that requires correction by replacement or re-fixing.

 Mark XXX for major mintake that cannot be corrected.

 9"unphatered area from SPL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/2".
- Provision of tiles in buthrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Will top must be of uniform thickness, correct height, at one level & without broken edges.

R	19	18	17	16	15	14	13	12	1	10	9	∞	7	6	S	4	w	2	-	GN
Remarks	Other	+	-	-	-	-	-	-	_		<u> </u>	妆		_		L	ļ .		_	S No Room
S	ier	Utility	Kitchen	Portico	Head room	Terrace/-balcony-2	Terrace/balcony-l	Lobby-2	Lobby-1-	Dining	Drawing	Toilet 4	Bedroom-4	Foilet-3	Bedroom 3	Toilet 2	Bedroom	Toilet 1	Bedroom	
				i	Ħ	balco	-batco					,	n-4		ή.	5	n 2	P	1	
1			en kraje			ny-2	my-l								`	7	8	47	MB)	,
			<	(!	1	ſ	1	J	<	<	{	1	1	[<	<	<	<	Skirting Provision (• or ×)
			1	((1	١	1)	1	<	ſ	1	1	l	<	<	ζ.	ς.	Finishing around door frame (v or x)
			<	\	1)	Ţ	J	1	<	<	١	1	j	ſ	<	<u>\</u>	<	~	Beams & columns finishing (• or ×)
	10		<	(1	1	(1	}	1	}	1	l	1	1	-	1	ſ	-	Finishing of lofts (\checkmark or \times)
			<	(/	\	1	}	1	<	۲		1	1	1	〈	<	<	<	Electrical junctions finishing (• or ×)
}			<	1		{	1	1	.]	1	5	{	1	1	1	<	<	<	<	Window check
-		-	<	1		})		1	1	1	1	1	1)	<)	<	1	Tiles provision (• or ×)
			<	Ţ	1	1	1	1)	1	1		})	1	<	1	<	1	Sink provision & size (• or ×)
-			ļ	!	1)	1	,)	\	<	1	1	1]	2	٢	<	<	Grooves for door frames (v or x)
				1.	1	١)	1)	1	}		1	})	1	١	1	1	Balcony & terrace sill top finishing 10 (v or X)
			1		1)))	1)	1	}	١	7		}	1	}	Screeding in bathroom & utility (• or ×)
				l)	1	}))	1	j	1)	5)			1	j	Screeding in 6" above FFL? (• or ×)

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	Good Avg. Bad
Plastering of compound wall & gate pillars (v or X)	
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Yes No
Plastering quality of paramet walls () or ()	
The state of the s	<
riastering and linishing of chajjas (v or x)	
Remarks:	