Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after su Proceed with further work only after making of the proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Villa No.
Submit ATR on QC re Proceed with work aft er work only after mak er work. ATR not requ		10.	acm	V. Cambrt	Conf (11P) Project	43
eport to QC team. Proceed ter submitting ATR or cing corrections pointe tired.	MD Sign	34040	Sign	Sign	Project	Stage
scommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.		Report filed and signed by PM?	₹P	V. dukah	GoV	
by QC. n. ATR not required.	For filling	ed by PM?	Date	Date	Phase	Sl. No.
	□Yes □No	✓ Yes □ No	20/08/19	20 00 19	X	34228

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting. tiling & flooring.

Plastering Check.

- Mark ✓ for correct or miner mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.

 Mark X X for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2 "grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

	R	_	<u> </u>	-	_	_						9		7	6	S		T	Τ,	T	+
	Remarks	19	-	 	 	-	-	13	-		10	_	<u> </u>	<u> </u>	_		4		2		S No
	urks	Other	Utility	Kitchen	Portico	Head room	Terrace/ balcony 2	Ferrace / balcony 1	Lobby 2	Lobby 1	Dining	Drawing	Toilet 4	Bedroom 4	Toilet 3	Bedroom 3	Toilet 2	Bedroom 2 以5		Bedroom 1 1415	Room
·				۷.	Î	۲,	1	7	5)	i		<	r i i	7	,	b I	Z	ζ,	۷.	<.	Skirting Provision (• or ×)
				4		<u> </u>		1	, -		9	۷,	San-	C v 3	Services.)	۲.,	K,	<u> </u>	<	Finishing around door frame (• or ×)
				_	۷,	۷.			b	i	4	۷.	E-104		ĺ	4	<	<,	<.	!	Beams & columns finishing (v or x)
				<	9	3	į	;		ì	1	,		1	e j	7		e e		7	Finishing of lofts (v or x)
					۷,	۷,		N	ì	;	2	< <u></u>	, m. 1-r	7	1		<	< .	٧.	۲,	Electrical junctions finishing (v or x)
				<	e .	Į.	ţ	1	1.	ì	<	۲,	C.W.	Sp. it is	Commen	E Constant	۷,	<>	. / .	۲,	Window check (• or ×)
				4	-	4	Classic	1	N. Carlot		B	1	2	P-100-8	Ĭ	C Zilliane	<	(5)	<	p. Mar. Comme	Tiles provision (• or ×)
				<	*)	1	3	ì	7	7.	9		1	1	1	1		1	Section 2.	e = 1.5 day	Sink provision & size
	-		4	<	1		1		1			۲,		in the second	ì	1 4			<.	<	Grooves for door frames (• or ×)
	-				1	C 50.00	3	1	ì	9	5,75)	n F	9	G-	1	t e	6-1	C	j.	Balcony & terrace sill top finishing 10 (v or x)
					7	10 mm	li con)		2° strane	Company of the Compan	2	7	3	Q.		ĵ	11	11-6	1	Screeding in bathroom & utility (v or x)
				7	Constant Constant		7.00	# C .	?		Company of the Compan	7	Dr. J.	7	Date:	500	6	0,	1250		Screeding in 6" above FFL? (• or ×)

Quality Control Check Repot. Stage: After Plastering (Villas)

Overall quality of plastering? Plastering of compound wall & gate pillars (• or ×)	Good Avg. Bad
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	√ Yes No
Plastering quality of parapet walls (vor x)	
Plastering and finishing of chajjas (vor x)	
Remarks:	***