Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	Previous stage report no.				Block No
TR on QC report to with work after subnuly after making conTR not required.	MD Sign	30103	Pushattom	S. Kulderp	SOV(LLP)	9.5
QC team. Procenitting ATR on rections pointed	gn		Sign	Sign	Project	
ed only after recheck l QC report to QC team. out in the QC report.		Report filed and signed by PM?	A	Shrefule	SOV	
by QC. n. ATR not required.	For filling	d by PM?	Date	Date	Phase	SI. No.
	☐Yes ☐No	✓ Yes No	26/06/2018	26/06/2018	[,]	20657

Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam.

 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark.

 Prepare plinth beam Dimensions Check Plan as follows:

 a. Show outer dimensions. (Tolerance 2")

 b. Show length and width of plinth beams (Tolerance 1")

- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

		Time Beam Diffensions Check Fian enclosed?	Raam
		Yes No	
•	.,3		

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good ☐ Avg. ☐ Bad
Have rods for staircase slab been provided?	✓Yes □No
Quality of Bracing Provided?	☐ Good ☑ Avg. ☐ Bad
Alignment of beams on outer side?	☐ Good Maye. ☐ Bad
Brackets for elevation features provided?	□Yes □No ☑NA
Level marking at 2' above FFL is made?	✓Yes □No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Pedestal/column0 – self check report attached?	☐Yes ☐No
Remarks:	

Plinth Beam Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XXX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	0.	, .	n .	۷ .	2 .	٠.	S No
	Depth and width of beams	Covering blocks for beams	Steet Check - Beams Bearing	Sieer Clieck - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	<		(<	<	7	(Quantitative Check (• or ×)
	Good Avg. Bad	Good Avg. Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good [☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Qualitative Check (Good / Avg. / Bad)