Ouality
Control Check
Check Ro
Repot.
Stage: A
fter Plas
stering (
(Villas)

Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by S. S.W.	Company	Villa No.	
IR on QC report to QC team. I with work after submitting ATI dy after making corrections po TR not required.	MD Sign	39914	20 Kign Hugsain Sign	S. Sund Kumps Sign	Project	Stage	
roceed only after recheck by ton QC report to QC team. Inted out in the QC report. AT	Fo	Report filed and signed by PM?	JON D	D	AVR Gulmorus Phase	SI.	
QC.	For filling Y			Date	hase	No.	
	Yes No	Yes Livo	85/04/19	25 04 19		33462	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

- Mark v for correct or minor nustake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.

  Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have "grooves.
- 10. Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	19	18	17	16	15	14	13	. 12	11	10	9	∞	7	6	Ŋ	4	w	2	-	S No	1
Remarks	Other	Utility	Kitchen	Portico	Head-room	Terrace/balcony-2-	Terrace / baleony 1.	Lebby-2	Leabby 1- F- LOWA		Drawing	Toilet4	Bedroom-4	Toilet 3 K- +O	Bedroom 3 A. Pod	Toilet 2 M. To	Bedroom 2 M. Red	Toilet 1 G. Tol.	Bedroom 1 6 - Bed	Room	
			<	)	1	1	<	1	ς	ζ	<	J	)	<	V	<	(	5	5	Skirting Provision ( • or *)	
			<		-	-	7	)	(	ζ,	ζ	1	1	<	<	(	ς	(	(	Finishing around door frame ( v or x)	
			(	1	1	1	(	1	(	ζ	ς	4	1	<	ζ	<	(	\	(	Beams & columns finishing ( v or x)	
			١	1	1	1	1	)	1	{	1	0		_	1	\	-	F-774	j	Finishing of lofts (v or x)	
			ς	1	1	1	<	1	ς,	ζ	ζ	1	1	<		(	(	(		Electrical junctions finishing ( v or x)	
			5	1	1	1	1	<b>,</b>	١	ζ,	5	garden.	•	ς,	<	ζ	ζ	<	(	Window check ( • or ×)	
			<	1	1		1	}	1	•	}	1	1	X	1	ř	-	X	1	Tiles provision ( • or ×)	
			ζ	•		1	1	1	-	1	1	1		1	1	Charles	1=	-	**************************************	Sink provision & size	
			ς	1		1	(	)	ς	}		1	1	<		ζ		ζ	<	Grooves for door frames (✓ or ×)	
			1	-	1	1	ς	1	1				1		)	,	diam's	{	•	Balcony & terrace sill top finishing 10 ( v or x)	
			1		1	1	5	1					1	K	1	Χ	-	i	1	Screeding in bathroom & utility ( • or ×)	
			)	)	)		<	٦ <b>ا</b>		)	)		1	3	]	Z	MA TONO	j	)	Screeding in 6" above FFL? ( • or ×)	

## Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	Good Avg. Bad
Plastering of compound wall & gate pillars ( ✓ or ×)	(
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	☐Yes ☐ No
Plastering quality of parapet walls (✓ or 🗙)	5
Plastering and finishing of chajjas (✓ or 🗙)	ς .
Remarks:	
	The state of the s