Hock No    Sign   Sign   Date   C6-c9-18	Ø	Quality Control Check Repot.	1	Stage: Before Casting Plinth Beam (Villas)	nth Beam (Villas)	
Sign  Sign  V. S. K. M. Date  Date  Sign  Report filed and signed by PM?  Sign  For filling  to QC team. Proceed only after recheck by QC.  bimitting ATR on QC report to QC team.  corrections pointed out in the QC report. ATR not required.	Block No	চ			SI. No.	31405
Sign  Sign  Report filed and signed by PM?  Sign  Report filed and signed by PM?  For filling  to QC team. Proceed only after recheck by QC.  bimitting ATR on QC report to QC team.  corrections pointed out in the QC report. ATR not required.	Company	VOC (LLP)	Project	Yec	Phase	1
Sign  Report filed and signed by PM?  Sign  Report filed and signed by PM?  For filling  to QC team. Proceed only after recheck by QC.  Ibmitting ATR on QC report to QC team.  corrections pointed out in the QC report. ATR not required.	Prepared by	V. Sanketh	Sign	V. Saxali	Date	81-60-90
Report filed and signed by PM?  Sign  For filling  to QC team. Proceed only after recheck by QC.  sometiting ATR on QC report to QC team.  corrections pointed out in the QC report. ATR not required.	Project Manager		Sign	- <del> </del>	Date	81-60-90
Sign  For filling  to QC team. Proceed only after recheck by QC.  sorrections ATR on QC report to QC team.  corrections pointed out in the QC report. ATR not required.	Previous stage report no.		0257	Report filed and signe	d by PM?	✓Yes □ No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	MD S	ign		For filling	☐ Yes ☐ No
Proceed with further work. ATR not required.	Recommendation:  Stop further work. Submediate Stop further work. Proceed with further work.  Proceed with further work.	iit ATR on QC report to eed with work after subrik only after making corrk. ATR not required.	QC team. Procenitting ATR on rections pointed	eed only after recheck QC report to QC team I out in the QC report.	by QC. ATR not required.	

## Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam.

  Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam. Dimensions Check Plan as follows:

  a. Show outer dimensions (Tolerance 2")

  b. Show length and width of plinth beams (Tolerance 1")
- Print an A3 size plan.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

  Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Plinth Beam Dimensions Check Plan enclosed?	✓ Yes □ No
	,

## Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting?  Quality of centering, rod bending and concreting?  Have rods for staircase slab been provided?  Quality of Bracing Provided?  Alignment of beams on outer side?	Good Avg. Bad Yes No Good Avg. Bad Good Avg. Bad No No No
Alignment of beams on outer side?	Good May Avg. Bad
Brackets for elevation features provided?	☐ Yes ☐ No ☑ NA
Level marking at 2' above FFL is made?	✓ Yes □ No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Pedestal/column0 - self check report attached?	✓ Yes
Remarks: NOTE: Mud not levelled Proporty inside or	and outside of
villa.	

## Plinth Beam Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction Mark x for minor mistake that requires minor correction.

  Mark x for major mistake that requires correction by replacement or re-fixing. Mark x x for major mistake that cannot be corrected.

  Columns overlapping length should be 45 to 50 D.

## Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	3.	2.		S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	4	~	_	~	~			Quantitative Check
	☐ Good ☑ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bau	Good Avg. Bad	COOM KI AVE. L. David	✓ Good Avg. Bad	W WOOD AVE. Dan	God Avg Bad	Qualitative Check (Good / Avg. / Bad)