anager stage report no. By MD on endation: urther work. Su further work. Pred with further to	Q	Quality Control Check Repot.		Stage: Before Casting Plinth	nth Beam (Villas)	
ACHH Sign Sign Date 2. Kul Leep Sign ND Sign Report filed and signed by PM? MD Sign MD Sign Report filed and signed by PM? For filling Report to QC report to QC report to QC report. ATR not required.	Block No	, s	1		SI. No.	3)487
Sign Sign Date Sign Arch Hossin Sign Sign Report filed and signed by PM? All Sign MD Sign Report filed and signed by PM? All Sign Report filed and signed by PM? For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required.	Company	INA	Project	AVE Homes	Phase	
ort no. 2 Krût HOSCO'N Sign Report filed and signed by PM? MD Sign MD Sign Report filed and signed by PM? For filling For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required.	Prepared by	Circulater	Sign	Engline	Date	8, (60/01
ort no. Sign Report filed and signed by PM?	Project Manager	Darra Hossain	Sign	Joseph -	Date	81/60/01
MD Sign For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required.	Previous stage report no.		1 7 CM 2.	Report filed and signe	ed by PM?	Yes UNO
rk. Submit ATR on QC report to QC team. Proceed only after recheck by ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. AT	Clasted B. MD on	MDS	ion '		For filling	☐Yes ☐No
ork. Submit ATR on QC report to QC team. Proceed only after recheck by ork. Proceed with work after submitting ATR on QC report to QC team. further work only after making corrections pointed out in the QC report. AT	Checked by me on					
Proceed with further work. ATK not required.	Recommendation: Stop further work. Subn Stop further work. Proc Proceed with further wo Proceed with further wo	nit ATR on QC report to seed with work after sub rek only after making co rek. ATR not required.	OC team. Promitting ATR or rections point	oceed only after recheck on QC report to QC team ed out in the QC report.	by QC. ATR not required.	

Notes:	Plinth
	Beam
	Check

- Inspection should be done before casting of plinth beam.
 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark Prepare plinth beam. Dimensions Check Plan as follows:

 a. Show outer dimensions. (Tolerance 2")
 b. Show length and width of plinth beams (Tolerance 1")

- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.
- Plinth Beam Dimensions Check Plan enclosed? Yes No

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

side the villa.	Remarks: Mudhave to be levelled inside and outside the villa
15	Pedestal/column0 - self check report attached?
Collect Iscars correction	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)
Compat Needs correction	Level marking at 2' above FFL is made?
L Ico L No E Live,	Brackets for elevation features provided?
No NA NA	Alignment of beams on outer side?
Good Nava Rad	Quality of Bracing Provided?
Yes No	Have rods for staircase slab been provided?
Good ☑Avg. ☐ Bad	Quality of centering, rod bending and concreting? Quality of centering, rod bending and concreting?

Plinth Beam Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark x for minor mistake that requires minor correction.
 Mark x for major mistake that requires correction by replacement or re-fixing.
 Mark x x for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

	Kemarks:		7	6.	5.	4.		ادر	2.	1.	S No
		Logical series	Denth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beatits Cyclapping w Common	Comp Owerlanning & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Îtem
			7								Quantitative Check (• or ×)
			Good Avg. Dau	Dod Dod	Good Avg. Bad	Good Avg. Bad	Good Avg. Bad	Good Avg. Dau	Dod.	Good Avg. Bad	Qualitative Check (Good / Avg. / Bad)