 0
<u>ual</u>
ity
C_{0}
ntro
) <u>{</u>
he
ck]
y Control Check Repot.
ot.
epot. Stage: Af
S
Stage
e
After
C
lumi
_
" C
1 Castin
Stage: After Column Casting (v

Block No.	77	Column No.	02	Sl. No.	32704
Company	Str (LLP)	Project	50V	Phase	R
Prepared by	J. Sai Kurri	Sign	GU,	Date	21/1/19
Project Manager	K. Purshotrom Sign	Sign	X	Date	61/1/18
Previous stage report no.	no.	32358	Report filed and signed	d by PM?	QYes □No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation: Stop further work. S Stop further work. I Proceed with further Proceed with further	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Ystop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n. Proceed with further work. ATR not required.	port to QC team. Proceer submitting ATR on ing corrections pointectied.	eed only after recheck l QC report to QC team. I out in the QC report.	y QC. ATR not required.	

Columns Position Check.

Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab. Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.
- rent dimension 14 0.00

Columns Position Check Plan enclosed?		
	Γ	Columns Position Check Plan enclosed?
	Offect diniension with red colour and mention actual dimension next to it.	. Chele each incollect

Slab Dimensions Check.

Notes:

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show inner dimensions of ducts and lift well. (Tolerance 1") Show length and width of balconies (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.

Specified thickness of slab?	Slab Dimensions Check Plan enclosed?	2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and men
Actual thickness of slab?	⊠Yes □No	a incorrect dimension with red colour and mention actual dimension next to it.

Quality Control Check Repot. Stage: After Column Casting (villas)

Good WAvg Bad
☐ Good ☑ Avg. ☐ Bad
☐ High ☐ Medium. ☐ Low
☐ Good ☐ Avg. ☐ Bad
√Yes No
and the second s
Good VAvo Rad
L tar

Columns height, plumb, steel & level marking check, Notes:

Mark V for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.
 Tolerance: Plumb 0.25".
 Circle actual height of columns if level differs from specified height by more than 1".

20.	19.	18.	17.	16.	15.	14.	13.	12.	11.	10.	9.	8.	7.	6.	5.	4.	3.	2.			SNo
																77	43	L.	Ŵ		Col No.
																CH	C3	5	C)		Col type
															[*****	114.8	14.8	8.구"	元	spec.	Height in ft
																1 : 1	= 7	7.10"	7.	Acmai	t in ft
																<	5	5	ς,	rods	Steel (
		N-655														<	<	<	~	rods	Steel (v or x)
								100								<	<	<	ζ,		Honeycombs
																`	<	<	7	Side I	Plumb
																<	<	?	5	Side 2	Plumb (✓ or ×)
☐ Yes ☐ No	☐ Yes ☐ No	☐Yes ☐No	☐Yes ☐No	☐Yes ☐No	☐ Yes ☐ No	☐Yes ☐No	☐Yes ☐No	□Yes □No	☐Yes ☐No	□Yes □No	☐Yes ☐No	☐Yes ☐No	☐Yes ☐No	□Yes □No	☐Yes ☐No	□Yes □No	✓Yes □No	☐Yes ☐No	☐Yes ☐No	column?	Reference level