Quality Control Check Repot. Stage: After Column Casting (villas)

Company Column No. O3 SI. No. 32729 Company Configuration Column No. O3 SI. No. O3 O3 O3 O3 O3 O3 O3 O						
Soy (LLP) Project Sign Sign Sign Sign Phase Date Phase Date Date Date Date Charles and signed by PM?	Block No.	90	Column No.	03	Sl. No.	32729
Sign Sign Sign Sign Date Date Date Date Date Control of the control of t	Company	SOV (LLP)	Project	ڻ ک	Phase _	×
Sign Character Sign Character Date 32229 Report filed and signed by PM? MD Sign MD Sign Report filed and signed by PM? For filling For filling For filling Proceed only after recheck by QC. roceed with work after submitting ATR on QC report to QC team. work only after making corrections pointed out in the QC report. ATR not required. work, ATR not required.	Prepared by	V. Sankoth	Sign	V. Cartes	Date	23/01/19
MD Sign Report filed and signed by PM? MD Sign For filling For	Project Manager	K. Purshalham	Sign	10	Date	23/01/19
MD Sign For filling ork. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Previous stage report r	no.	32229	Report filed and signe	d by PM?	⊠Yes □No
ork. Submit ATR on QC report to QC team. Proceed only after recheck by QC ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR urther work. ATR not required.	Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
	Recommendation: Stop further work. Stop further work. Proceed with further	Submit ATR on QC re Proceed with work aft er work only after mak er work. ATR not requ	port to QC team. Procester submitting ATR on ing corrections pointed ired.	ced only after recheck b QC report to QC team. I out in the QC report.		

Column Position Check.

Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab. Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.
- Columns Position Check Plan enclosed? Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it. ⊠ Yes

L Z

Slab Dimensions Check

Notes:

- 1. Prepare Slab (or plinth beams) Dimensions Check Plan as follows: Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.

Quality Control Check Repot. Stage: After Column Casting (villas)

Columns height, plumb, steel & level marking check.

- Mark v for correct or minor mistake which does not require correction

 Mark x for minor mistake that requires minor correction.

 Mark x for major mistake that requires correction by replacement or re-fixing.

 Mark x x for major mistake that cannot be corrected.

 Tolerance: Plumb 0.25".
- Circle actual height of columns if level differs from specified height by more than 1".

1	20.	19.	18.	17.	16.	5.	į.	14	13	12.	11.	10.	10	9.	8.	7.	ı ç	۲ :	5	4	ယ	2.	!-	•		SNo
													-								1	13 Y	132			Col No.
-																			()	5	C2	ري (ع	C3			Col type
																			8-4	5 - (1 C-12	2-1-10 0-1-10	ू है- 2		Spec.	Heig
																			8-7	2 2 2 2	0 7 7 1 1	nt: 19	8.80		Actual	Height in ft
																	-			<			<.	rods	No of	Steel (
							-												<	<	*			rods	Size of	Steel (or x)
																			<	<	,		<			Honeycombs
																			<	<					Side 1	Plumb
																			<	×.	<	, ,			Side 2	Plumb (v or x)
□ Yes □ NO	1	$\neg \mid \vdash$	71		$\neg \Gamma$	$\neg $	□Yes □No	☐Yes ☐No	∐Yes ∐No	□ res □ no	7	☐Yes ☐No	☐Yes ☐No	∐ Yes ∐ No	16][Yes No	☐Yes ☐No	Yes No	ılr	7/		√ Yes ☐ No	column?	marked on	Reference level