## Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Villa No.
stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.		no.	Balamorals Sign	P. Sais Keway	アスス	53
eport to QC team. Proceed ter submitting ATR on the corrections pointedired.	MD Sign	29197	Sign	Sign	Project	Stage
eed only after recheck QC report to QC team do out in the QC report.		Report filed and signed by	Jan Villan	Pridy	Bloomdale	
by QC.  ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	☐ Yes ☐ No	LYes □No	81/5/18	8)   5   8 ;	)	44208

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

- Mark v for correct or minor mistake which does not require correction

  Mark X for minor mistake that requires minor correction.

  Mark X x for major mistake that requires correction by replacement or re-fixing.

  Mark X X for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance '4". Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

		Т	Т		T	_	1		T	1	ſ	1	1	1	1	ή			·)			_	_
Screeding in 6" above FFL? (v or x)		.   {	1	١	(	. \		1	1	)		(		1		· )	1						
Screeding in bathroom & utility (vor x)		l	(	(	1	,				1		(	{	}			1						
Balcony & terrace sill top finishing 10 vor x)			(	j	1		l	1		1		(	l	\	I		1			_			
Grooves for door	>	`	`		} {	S	pr		>	1	(	(		(	j	ĺ	}						
Sink provision & size (v or x)	(	>	. (	>			ĺ	1	ſ	1		{	1.		Ì	1	5						
Tiles provision (x 10 v)	ĺ	>	, (	>	, (		,	( i	J	ļ	{	(		{	(	1	>						
Window check (v or x)	"	}	\	>	(		l	1	>	>	į	į			1	)	>						
Electrical junctions finishing (v or x)	>	>	>	>	(	{	1	1	7.	4	(	(	(	(	(	İ	>						
sfiol do gaidsinia (x vo v)		(	(	(	1	١	-		(	{		j			1	Į	>						
Beams & columns finishing (v or x)	,		`	>	(	(	(	1	>	/	(	(	{	(	(	\	>						
Finishing around door (× 10 v) entert	`	~		>	Ţ	1	Ĭ		>	<b>f</b>	-	\	İ	1	1	1	>		_				
noisivor¶ grirting Provision (× 10 ∨)	>	/ /	`	>	\$	(	(	\	N	×	(	(	(	}	١	-	$\nearrow$						
Коот	Bedroom 1 MB	Toilet 1 MS	22	Toilet 2 C 介	Bedroom>3	Toilet 3	Bedroom 4	Toilet 4	Drawing	Dining	Lobby 1	Lobby 2	Terraee/balcomy 1	Terrace/batcony 2	Head room	Portico	Kitchen	Utility	Other	arks			
on s		7	ヿ		2	9	7	∞		_	11	-	$\dashv$	_	-	_			6	Remarks	100 100 100		

Stage: After Plastering (Villas)

Quality Control Check Repot.

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	Good Navg. Bad
Plastering of compound wall & gate pillars ( or x)	AVS.
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	√Yes No
Plastering quality of parapet walls ( or x)	KZ
Plastering and finishing of chajjas ( or X)	F-7-4
Remarks:	2