	Quality Contr	Quality Control Check Repot.	Stage: After Column Castin	Casting (villas)	
Block No.	96 85	Column No.	10	SI. No.	24566
Company	Voc Lui)	Project	200	Phase	)
Prepared by		Sign	200	Date	15/2/18
Project Manager	D. Surel	Sign		Date	15/2/18
Previous stage report no.	no.	78814	Report filed and signed by	d by PM?	Yes No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Stop further work Proceed with furth Proceed with furth	Commendation:  Stop further work. Submit ATR on QC report Stop further work. Proceed with work after some Proceed with further work only after making Proceed with further work. ATR not required.	port to QC team. Proceed the submitting ATR or ing corrections pointe ired.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.	by QC. ATR not required.	
Columns Position Check Notes:  I Impection should be done in the context of the c	umns Position Check. ss: Impection should be done after easting of column	s at each stage and before	umns Position Check.  SS: Imprecion whould be done after casting of columns at each stage and before starting centering works for each slab.	each sìab.	
<ul> <li>a. Divide blocks into sn</li> <li>b. Show size and orient</li> <li>c. Show inner – inner sq</li> <li>d. Show diagonals for 2</li> <li>e. Print an A3 size plan.</li> </ul>	Divide blocks into smaller sub-blacks.  Show size and orientation of columns. (Tolerance 0.5")  Show inner—inner space between columns. (Tolerance 1")  Show diagonals for 20% of bays. (Tolerance 1.5")  Print an A3 size plan.	olerance 0.5") ns. (Tolerance 1") nce 1.5")			
3. Circle each correct dimension with green co Columns Position Check Plan enclosed?	nension with green colour. (ck Plan enclosed?	Circle each incorrect dimer	Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.  umns Position Check Plan enclosed?    Ves   No	ntion actual dimension nex	ct to it.
Slab Dimensions Check. Notes:	<u> </u> k				
Prepare Slab (or plinth     a. Show outer d     b. Show length:     c. Show inner d	Prepare Slab (or plinth beams) Dimensions Check Plan as follows:  a. Show outer dimensions of slab. (Tolerance 2")  b. Show length and width of balconies (Tolerance 1")  c. Show inner dimensions of ducts and lift well. (Tolerance 1)	Plan as follows: to 2") stance 1") tolorance 1")			
	Still well (Lolerance I'')	vell. (Tolerance I")			

Quality Control Check Repot.

Actual thickness of slab?

1

2. Circle each correct dimension with green of Slab Dimensions Check Plan enclosed?

Print an A3 size plan. Show location of sunken slab.

Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Yes

No

7

Specified thickness of slab?

## Quality Control Check Repot. Stage: After Column Casting (villas)

		Remarks:
Dau	LyGood L Avg. L	Quality of infrastructure for curing.
_]]		Is the pressure in the curing pipe more than 15' head?
	13	Frequency of curing in number of times a day (enquire from labourers)
	10 10 1	Distance of tap from furthest distance that requires curing. (max permitted 100')
	✓ Yes ☐ No	Gunny bags used for column curing?
	┧╒	Drum (200 lts) provided for curing?
7		Bund also ia leas than 100 aft?
た日	No.	Bunds for curing made on slab?
		Remarks:
Tes Live		Have 6 cubes each for columns and slab casted and numbered for testing?
Vor	than 1"	Number of beams that are sagging, bulging, caved or deflected in the slab by more than I
		Are the honey combs is slab and columns packed?
Good Avg. Bad		Number and size of honey combs'!
High Medium. Low		Quality of starters?
Good Avg. Bad		Zumit) or concession
Good Avg. Bad		Quality of centering, rod bending and concreting?

## Quality Control Check Repot. Stage: After Column Casting (villas)

## Columns height, plumb, steel & level marking check.

- Mark v for correct or minor mistake which does not require correction
   Mark X for minor mistake that requires minor correction.
   Mark XX for major mistake that requires correction by replacement or re-fixing.
   Mark XX for major mistake that cannot be corrected.
   Tolerance: Plumb 0.25".

SNo Circle actual height of columns if level differs from specified height by more than 1".

No | Col No. | Col type | Height in ft | Steel ( or x)

					1				Γ-	T-	1	1	-			- 10	-							25
	20.	19.	18.	17.	16.	15.	14.	13.	12.	11.	10.	, ,		<b>∝</b>	, ,	•	2	4.	ω	2.	ļ :-	_	H\$	2
									23	7	7	CH	(,		- *		2	Pe .	びょ	Z,	7	7	<u>.</u>	-
									Ch	C	CI	G	( 1)	, <del>-</del>			77	C	1	63	C			of the
									114.0			-88			→	- [k		3_X	3 0	ر ا ا	4		Spec.	31211
								-	0,0,	× 4 "	\ "(\frac{1}{2} )"	8, Y"	8.11	T.	-	١ از	7	200	0 0	21.1	が		Actual	rierBrit m II
		_						,		ς,	<		<	•	· <	. <	<		<			rods	No of	Steel
								<		ζ,		5	۲,	₹	र्	<	, <	. <	, <	7	5	rods	Size of	Steel ( or x)
								<	<	`\			i.	ζ'	· ·	メ	K	<	K	,				Honeycombs
								<	K		,	<u> </u>	•	۲	₹.	<	7	<	<	<		Side I	0.1	Plumh
								<	Ş	k	~	<		•	<	ζ.	<	5	<	\ \	Š	Side 2	2 2	Plumh ( ~ or v)
∐Yes □No	∐Yes □No	∐Yes □No	∐Yes ∐No	∐Yes ∐No	∐Yes □No	∐Yes □No	∐Yes □No	LyYes UNo	ılı	1 -	7	]! -		Yeu No	[VYes    No	Yes No	□Yes □No	LyYes □ No	Yes No	TW res Lino	7	column?	reference level	Deference lavel
										•	72					1	!		Ь	L			-	