Quality Control Check Repot. Stage: After Plastering (Villas)

| Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required. | Checked By MD on | Previous stage report no. | Project Manager | Prepared by | Company | Villa No. |
|--|------------------|--------------------------------|------------------|-------------|------------------|-----------|
| ubmit ATR on QC re roceed with work af work only after mak work. ATR not requ | | | G. Cursesh Kumas | 1- Sanketh | Nilsioni Estatos | 179 |
| eport to QC team. Proter submitting ATR oring corrections point ired. | MD Sign | 34098 | Sign | Sign | Project | Stage |
| ecommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required. | , | Report filed and signed by PM? | (italest | J-Sukut | Nilaiou Estates | |
| by QC. 1. ATR not required. | For filling | ed by PM? | Date | Date | Phase | Sl. No. |
| | ☐ Yes ☐ No | Yes No | 12/12/19 | 12/12/19 | | 5+246 |

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- 1. Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance ¼".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have ½"grooves.
- 10. Sill top must be of uniform thickness, correct height, at one level & without broken edges.

| Ren | 19 | 18 | 17 | 16 | 15 | 14 | 13 | 12 | 11 | 10 | 9 | × | 7 | 6 | 2 | 4 | ယ | 2 | | S No |
|---------|-------|---------|------------|----------|-------------|--------------------|-------------------------------------|---------------|---|-----------|----------|---------------|---------------|----------|-----------|----------|------------------|-------------|--------------|--|
| Remarks | Other | Utility | Kitchen | Portico | Head room | Ferrace/ balcony 2 | Terrace / balcony 1 | -Lobby 2 | Lobby 1 | Dining | Drawing | Toilet 4 | Bedroom 4 | Toilet 3 | Bedroom 3 | | Bedroom 2 KB | Toilet 1 MT | Bedroom 1 NE | Room |
| | | | ۲. | • | 4 | | | | 4. | <u> </u> | √ | | | | 94. 1 | 1 | 1 | */ | 4 | Skirting Provision (• or ×) |
| | | | V | * | 4 | * -0 | | | 3 | | Ų, | | | | | 1. | ./ | 1 | 1. | Finishing around door frame (• or ×) |
| | | | < | <u> </u> | 4 | ٠. | | i | : | 4 | <, | , | | *** | | 1 | <i></i> | 1 | 1 | Beams & columns finishing (• or ×) |
| | | | 2 | B-51 | cost 🗸 | 2000 | **** | ŀ | p. 47ma | | * 1 | | A | | ì | Service. | 1 | - T- 196 | 2 | Finishing of lofts (• or ×) |
| | | | ۷_ | ۷_ | ζ., | | 1 1000 | | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | ۷, | 4 | | ā | | | | 4 | .J | \ | Electrical junctions finishing (v or X) |
| | | | <u></u> | great 6 | 9. | *** | .) | a grant and a | | ~ | 4 | ¥ | | 100 | | F | 4 | 4 | ζ, | Window check (✓ or ×) |
| | | | <i>ح</i> ہ | 57.6 | *, ****** | | | والمسا | | | # | To the second | | | i | 4 | a kerena | 4 | Ŗ, | Tiles provision (• or ×) |
| | | | < | , | | | principal designation of the second | , , , | | • | I | 2 | ľ. | - C | | 0.000 | d | Ţ | F-7 | Sink provision & size (✓ or 🗙) |
| | | | < | 4-7 | 4. | ÷ . | in . | } | | | 4 | 2 | | - | Ì | 7 | 7 | 4 | 4 | Grooves for door frames (• or ×) |
| | | | | A | e | · · | | 1 | 1 | • | A | | in the second | İ | | 2 | e vi | tar-17 | خما | Balcony & terrace sill top finishing 10(• or ×) |
| | | | 1 | 1 | a promote a | Ŷ. | r i | 1 | j | Ry action | 5. | | 7 | | : | e l | , (₁ | į | , e.e.) | Screeding in bathroom & utility (• or ×) |
| | | | - | 5 | £.5 | i | | | : / | | 6-57) | | | | | | | Care | 2.3 | Screeding in 6" above FFL? (• or ×) |

Quality Control Check Repot. Stage: After Plastering (Villas)

| | | Т | T | Т | | 7 | 7 |
|--|----------|---|---|---|--|--------------------------------|---------------------|
| | Remarks: | Plastering and finishing of chajjas (• or ×) | Plastering quality of parapet walls (• or ×) | Is plastering of compound wall and villa external walls 6" below FFL of setbacks? | Plastering of compound wall & gate pillars (• or ×) | Overall quality of plastering? | Miscellaneous check |
| | | | _ | Yes No | | Good Avg. Bad | |
| | | | | | | | |