## Quality Control Check Repot. Stage: After Plastering (Villas)

Villa No.	ر در در	Stage	1	SI. No.	34829
Company	411 22A	Project	V°C	Phase	-
Prepared by	G RATESII Sign	Sign	N. S.	Date	03   D   10
Project Manager	M. SURES 11 Sign	Sign	( <del>\</del>	Date	C3 2 18
Previous stage report no.	no.	3 4465	Report filed and signed by	cd by PM?	LYes   No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work.	Submit ATR on QC	report to QC team. Pr	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.	, by QC.	
Proceed with furt	Proceed with further work only after making or Proceed with further work. ATR not required.	aking corrections poin	Proceed with further work only after making corrections pointed out in the QC report. ATR not required	ATR not required.	

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, sereeding in bathrooms is completed,
- before starting painting, tiling & flooring.

### Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.

  Mark XX X for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 3/2".
- Provision of tiles in balhrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hale should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	19	∞	17	2	15	14		W.240		10	9	8	7	6	5	4	3	2	1	S No
Remarks	Other	Otility	Kitchen	Portico	Head room	Terrace/-balcony-2-	Terrace / balcony 1	Lobby-2	Lobby 1 C. C	Dining	Buimer(I	Toilet4	Redroom 4		w		2		Bedroom 1 hi. 3	Room
		i	5	1	<	1	<	1	0 95		3 5	١	1	1	1	1	1	1	7	Skirting Provision (✓ or 🗙)
			<	1	ζ,	١	ζ.	ļ	}	}	5	1	1	<	ς	5	5	5	1	Finishing around door frame ( v or X)
			5	1	<	1	\	١	1	<	7	[	)	\	5	ς	<	<	<	Beams & columns finishing ( v or x)
			١	!	١	,	1	1	1	4	1	1	)	١	١	١	)	٦	1	Finishing of lofts
		1000000	<	1	5	1	\	١	-	<	1	1	1	<	5	<	<	<	4	Electrical junctions finishing ( v or x)
		ř	<	1	5	1	~	١	<	`	<	1	}	<	<	<	1	<	5	Window check (✓ or ×)
			<	١	)	1	1	١	1	}	1	1	1	<	1	<	1	5	1	Tiles provision (✓ or ×)
			1	1	١	1	١	١	١	1	1	1	١	1	ļ	1	ļ	1	}	Sink provision & size
	88		<	1	5		5	1		}	\	!	1	1	\	1	5	5	7	Grooves for door frames ( > or ×)
			1	1	ı	}	<	ļ	١	1	)	ļ	1	٦	ì	,	١	1	1	Balcony & terrace sill top finishing 10( v or x
		20000	١	3	5	1	١	ļ	1	1	١	1	١	ļ	1	<	1	5	1	Screeding in bathroom & utility ( v or X)
			1	1	<	]	١	)	1	1	1	ļ	1	1	١	<	1	<	)	Screeding in 6" above FFL? (v or x)

# Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	☐ Good ☑ Avg. ☐ Bad
Plastering of compound wall & gate pillars ( v or x)	1
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	☑Yes □No
Plastering quality of parapet walls ( v or X)	<b>4</b> ,
Plastering and finishing of chajjas (v or X)	,
Remarks:	
	On the Control of the