Quality Control Check Repot. Stage: Before Casting Plinth Beam (Apartments)

Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after so Proceed with further work only after making of the proceed with further work. ATR not required.	Checked By MD on	Cl. 1 15 3 C.	Previous stage report to	Project Manager	Prepared by	Company	Block No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	MD Sign For filling Yes No	34,905 Report filed and signed by PM? ☐ Yes ☑ No	Suddankeddy Sign Refer Date 28-12-2019	V. Surketh, Date 28-12-2019	Sion	Project Phase	((004, 005) - SI. No. 267

Plinth Beam Check.

- 1. Inspection should be done before casting of plinth beam.
- Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark.
- Prepare plinth beam Dimensions Check Plan as follows:
- Show outer dimensions. (Tolerance 2")
- Show length and width of plinth beams (Tolerance 1")
- Print an A3 size plan.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Plinth Beam Dimensions Check Plan enclosed?
V Yes □ No

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Apartments)

			Remarks: 1) (could a a la contraction of the contra	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Level marking at 2' above FFL is made?	Brackets for elevation features provided?	Alignment of beams on outer side?	Quality of Bracing Provided?	Have rods for staircase slab been provided?	Quality of centering, rod bending and concreting?	Quality of centering, rod bending and concreting.
		Losur, Docoll and Orl	_	✓ Correct ☐ Needs correction	▼ Yes	□Yes □No ☑NA	☐ Good ☑ Avg. ☐ Bad	V Good Avg. Bad	√ Yes □ No	☐ Good ✓ Avg. ☐ Bad	

Plinth Beam Steel check.

- Mark o for correct or minor mistake which does not require correction
 Mark o for minor mistake that requires minor correction.
 Mark o for major mistake that requires correction by replacement or re-fixing.
 Mark o for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Apartments)

Nemarks:	Domosile.	j c		٨	4.	3.		٤		S No
	Depth and width of beams	Covering blocks for beams	Siect Check - Beams Bearing	Stod Chall by a country of the count	Steel Check - Reams Overlanning & Cronting	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Stoci Check - Deall 110 OI TOUS	Steel Chook Doom to fee 1	Item
		~ }	< ,			<			(• or ×)	Quantitative Check
	√ Good Avg. Bad	☐ Good Avg. ☐ Bad	Good W Avg. Bad	№ Good Avg. Bad	Tan Cook Live & Land	W Good Ava Bad	✓ Good ☐ Avg. ☐ Bad	Good Avg. Bad	(Good / Avg. / Bad)	Qualitative Check