Recommendation: Checked By MD on Previous stage report no. Project Manager Prepared by Company Villa No. Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. A. SURES H 200 27 Quality Control Check Repot. Sign ∥ Project Stage MD Sign Sign 2220 Report filed and signed by PM? Stage: After Plastering (Villas) Phase Sl. No. For filling Date Date L/Yes C 34980 Yes W LVo No

2

5

Inspection should be done after:

Proceed with further work. ATR not required.

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check

- Mark v for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/4".
- All doors frames should have 1/2" grooves. Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Quality Control Check Repot. Stage: After Plastering (Villas)

Remarks:	Plastering and finishing of chajjas (v or x)	Plastering quality of parapet walls (or x)	rs plastering of compound wall and villa external walls 6" below FFL of setbacks?	Is plastering of compounts wan & gate pillars (v or X)	Plastering of compound wall & rote willow	Miscellaneous check Overall quality of plactering?
5			Yes No	7	☐ Good ☑ Avg. ☐ Bad	