## Quality Control Check Repot. Stage: After Plastering (Villas)

Villa No.	ナヤ	Stage	1	Sl. No.	81878
Company	Vilgivi estate	Project	Mlgin estate	Phase	#
Prepared by	M. Tya Sridhor	Sign	7	Date	11/20/91
Project Manager	Radheshan	Sign	Report	Date	16/05/17
Previous stage report no	no.	27019	Report filed and signed by PM?	d by PM?	Ycs NNo
Checked By MD on		MD Sign		For filling	Yes No
Recommendation: Stop further work. Stop further work Proceed with furth	Recommendation:  Stop further work. Submit ATR on QC report  Stop further work. Proceed with work after s:  Proceed with further work only after making of the proceed with further work. ATR not required	eport to QC team. Profer submitting ATR cang corrections point ired.	ccommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required Proceed with further work. ATR not required.	oy QC. ATR not required.	

### Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed
- before starting painting, tiling & flooring.

#### Plastering Check.

#### Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark X for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 'a"grooves.
- 10. Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	<u> </u>	$\frac{1}{\infty}$	17	16	15	4	13	12	_	10	9	8	7	6	5	4	w	2	-	S No
Remarks X.)	Other	Utility	Kitchen	Partieo	Head room	Terrace/balcomy-2	Terrace / balcony 1	Lebby 2	Labby-1	Dining	Drawing	Toilet 4	Bedroom 4_	Toilet 3	Bedroom 3		Bedroom 2 / 代分	Toilet 1 (MT)	Bedroom I (MB)	Room
Provision			<	1	1	1	1	١	ſ	<	<	-		J	1	<	<	ζ	<	Skirting Provision ( • or ×)
				1	ī	1	ļ	1	1	١	<	ſ	1	1	ſ	<	<	く	<	Finishing around door frame ( • or ×)
for De			<	1	1	1	1	Ţ	1	<	<	1	1	ſ	1	<	<	<	<	Beams & columns finishing ( v or x)
Dado	1000		<	1	1	ı	1	1	1	١	1	1	ſ	1	j	(		f	:	Finishing of lofts
the is			<	1	1	1	1	1	1	<	<	١	1	1	,	<	4	<	<	Electrical junctions finishing ( v or x)
			<	1	ſ	1	1	١	3	1	<	١	1	I	1	<	<	<	<	Window check ( • or ×)
Kitchen			j	1	1	1	1	I	J	1	1	1	1	}	1	<	1	<	1	Tiles provision
h'a			<	1	1	1	ļ	١	1	١	ļ	1	}	-		<	١	<	{	Sink provision & size
as not			1	1	1	١	1	1	ţ	1	<	1	1	]	•	<	<	<	<	Grooves for door frames ( v or x)
				1	)	1	}	1	ļ	1	[	ļ	1	1	}	1	ſ	1	j	Balcony & terrace sill top finishing 10 ( • or ×
ronded				1	1	1		1	]		1	١		)	J	1	j		ı	Screeding in bathroom & utility ( • or ×)
			1	)	,	1	J	1	,	1	)		]	1	1	1	. 1	1	1	Screeding in 6" above FFL? (✓ or X)

Quality Control Check Repot. Stage: After Plastering (Villas)

# Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	☐ Good M Avg. ☐ Bad
Plastering of compound wall & gate pillars (✓ or X)	`
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Yes No
Plastering quality of parapet walls ( v or X)	<
Plastering and finishing of chajjas ( vor x)	
Remarks:	