Quality Control Check Repot. Stage: After Column Casting (villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n V Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No.
mit ATR on QC receed with work af ork only after mak		C	Redheshyan	P. San Kun Sign	Milyon astrato	(;)
eport to QC team. Proc ter submitting ATR on cing corrections pointed tired.	MD Sign	ろよっとて	Sign	Sign	Project	Column No.
eed only after recheck QC report to QC team d out in the QC report.		Report filed and signed by PM?	To De	P/4	Milgan estato	70
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	S1, No.
	☐ Yes ☐ No	Wes No	7:12/85	4111/82	F1	74147

Columns Position Check.

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab.
 Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolcrance 1") Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.
- colour Circle each in ÷

,	_	نب
COMMING I COMOUNT CHOOM STATE CHOICE	Columns Position Check Plan enclosed?	. Circle each correct dimension with given colour. Circle each incorrect dimension with real colour and incurrent
	Yes	בכן מווויפוואוטוו איווי ובת בניוסח שות וובוויסוו שביתשו תחויבו ואיני ובי ניבי ור

Slab Dimensions Check.

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
 a. Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- Show location of sunken slab Show inner dimensions of ducts and lift well. (Tolerance 1")
- Print an A3 size plan.
- ect dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention ac	sion with red colour and mennon actual of	imension next to it.
Slab Dimensions Check Plan enclosed?	Yes No	
Specified thickness of slab?	Actual thickness of slab?	411/1

Quality of centering, rod bending and concreting. Quality Control Check Repot. Stage: After Column Casting (villas)

Quality Control Check Repot. Stage: After Column Casting (villas)

Columns height, plumb, steel & level marking check. Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.
 Tolerance: Plumb 0.25".
 Circle actual height of columns if level differs from specified height by more than 1".

20.	19.	18.	17.	16.	15.	14.	13.	12.	11.	10.	9.	,×		ń	٠٠.		'n	2.	ŗ			s No
			3 I									<u> </u>				\ \&	4	17.0	٦ ٢			Col No.
																ر ,	C 1	C-	-			Col type
															8	アンティ	8-7115	パーセ・8	111.8		Spec.	Heigh
					and the second s	319	8									77. So	8-216	×-%;	×2 ×2 =		Actual	Height in ft
		2500000	2000		20 M											<	<	<	5	rods	No of	Steel (
					30000		100		WARE TO			_				<	۷	<	Γ	rods	Size of	Steel (✓ or ×)
	200 M				00 miles was 00000 2000 NO 000000				3							7	1	ς.	ζ,			Honeycombs
																<	1	5	5		Side 1	Plumb
				20.00												<	5	\ '			Side 2	Plumb (or x)
☐Ycs ☐No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐Yes ☐No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐Yes ☐No	☐ Yes ☐ No	☐Yes ☐No	☐ Yes ☐ No	☐ Yes ☐ No	□/Yes □ No	Tyes No	Yes No	□ Yes □ No	column?	marked on	Reference level			