ATR on Quality Control Check Repot. (Bungalows)

7					
Bungalow No	183	QC report stage	Planth Languar	SI. No.	
Company		Project	1 10011		30921
Prenared hy	5		Nilgin Excels	Phase	b
Trepared by	P. Abwuch	Sign	P. DE Q	Date	14 10
Project Manager		Cian			101111111111111111111111111111111111111
Daniel DO 1	Machinerana	SIEII	N. Mal	Date	OV 17 176
Receipt by QC date	-	Sign		Other	8
Receipt at HO date		Cian	ī		
City of the Land		Sign		Other	
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation that was made by QC: Stop further work. Submit ATR on Q Stop further work. Proceed with wor	Recommendation that was made by QC: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team.	port to QC team. Proce	eed only after recheck b QC report to QC team.	y QC.	
Notes:			,		

- Attach a copy of the QC report to this sheet.
- Circle each correction with a red pen tick () each circle for work completed and cross () each circle where work has not been completed. Give remarks for each case where work has not completed on this sheet.

 Make 2 copied of the ATR send one to MD and other to QC.
- Enclose required photographs hard copy.

					Remarks:
, ,					MOON!
-				_	work complyted
					χψ
2					
3 · ·					
			a a		
7	.e., =		*	-	

	Quality Control Check Repot.		Stage: Before Casting Plinth]	th Beam (Villas)	
Block No	153			SI. No.	30921
Company	Nilling Estato Project	ject	Hilligh CXIST	Phase	(=)
Prepared by	P. Sai Kumai Sign	Ħ		Date	.25/3/19
Project Manager	Madhusudkan Sign	'n	Mightal	Date	814/52
Previous stage report no.	28079	19	Report filed and signed by PM?		No No
Checked By MD on	MI	MD Sign		For filling	Yes No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck be Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. In the Proceed with further work. ATR not required.	bmit ATR on QC report occed with work after work only after making	t to QC team. Prosubmitting ATR of corrections points.	ecommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	y QC. ATR not required.	•

Notes: Plinth Beam Check,

- Inspection should be done before casting of plinth beam
 Yellow enamel point to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark.
 Prepare plinth beam Dimensions Check Plan as follows:

 a. Show outer dimensions (Tolerance 2")

 b. Show length and width of plinth beams (Tolerance 1")

 c. Print an A3 size plan

P

inth Beam Dimensions Check Plan enclosed?	Circle cach correct dimension with green colour. Circle each incorrect dimension with red colour and incution actual officialistic facts of it.
UYes UNo	CO:OH CIN HERBER ACAMAN OF MENTS OF TEXAS AS IT.

Work can proceed to next stage. in the QC report have been completed. Certified that all corrections mentioned

MWM 26/8/18	M. M.	nadmilan-
Date	Sign	Project in-charge

	Remarks:
☐Yes ☐No	Pedestal/column0 - self check report attached?
YCorrect ☐ Needs correction	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)
Yes No	Level marking at 2' above FFL is made?
□ Yes □ No □NÃA	Brackets for elevation features provided?
Good Avg. Bad	Sufficient of hearits off office Side;
☐ Good ☑ Avg. ☐ Bad	A lignment of booms of the state of the stat
Yes No	Onality of Bracing Provided?
☐ Good ☐ Avg. ☐ Bad	Have rods for staircase slab been provided
	Quality of centering, rod bending and concreting. Quality of centering, rod bending and concreting.

Plinth Beam Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction

 Mark x for minor mistake that requires minor correction.

 Mark x for major mistake that requires correction by replacement or re-fixing.

 Mark x x for major mistake that cannot be corrected.

- Columns overlapping length should be 45 to 50 D.

20	
œ	
C	
W)
0	
-	>
W)