Company  Co	DIOCK NO	>				
Project  P. Sof Kurer Sign  Rolpshwar Lao  Sign  Nort no.  Sign  Phase  Phase  Phase  Phase  Phase  Phase  Phase  Phase  Phase  Port no.  Polynom  Phase  Phase  Port no.  Polynom  Phase		08	Column No.	0	Sl. No.	991.00
P. Sey Kurver Sign    Kolpshwar Leo    Sign	Company		Project	Dar	Phase	0.1418
ort no.  Sign  Coreshway Lao  Sign  Core no.  Coreshway Lao  Core no.  Core			Sign	0.7	Date	
ort no.  Date  Ort no.  292 44 Report filed and signed by PM?  MD Sign  MD Sign  Report filed and signed by PM?  For filling  For filling  rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  In ther work only after making corrections pointed out in the QC report. ATR not required.		1	2	101	200	8/2/82
ort no.  29244  Report filed and signed by PM?  For filling  For filling  Therefore, a fler submitting ATR on QC report to QC team.  In therefore, a fler making corrections pointed out in the QC report. ATR not required.	o) oor reminisor	Opshwar Rao	Sign	X STATE OF	Date	20/2/18
MD Sign  For filling  rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  In ther work only after making corrections pointed out in the QC report. ATR not required.	Previous stage report 1	no.	2000	Report filed and signa	d ke man	10 17 0
rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  rk. Proceed with work after submitting ATR on QC report to QC team.  In ther work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on			d	# 0) 1 1711.	TATES   NO
rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  ork. Proceed with work after submitting ATR on QC report to QC team.  In ther work only after making corrections pointed out in the QC report. ATR not required.	110 011		MID Sign		For filling	TYPS TIME
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	Recommendation:					
	Stop further work. Stop further work. Proceed with furth Proceed with furth	Submit ATR on QC reproceed with work after work only after making work. ATR not require	port to QC team. Proce er submitting ATR on ing corrections pointed red.	ed only after recheck by QC report to QC team. Out in the QC report. A	y QC. ATR not required.	

Quality Control Check Repot.

Stage: After Column Casting (villas)

Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab. Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show diagonals for 20% of bays. (Tolerance 1.5") Show inner - inner space between columns. (Tolerance 1")
- Print an A3 size plan.
- Columns Position Check Plan enclosed? Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.  $\mathcal{N}_{es}$ No

Slab Dimensions Check.

Notes:

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- ġ.c Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Sis Circle each correct dimension with green colour. Circle each ir

	Specified thickness of slab?	The state of the s	Slab Dimensions Check Plan enclosed?
M 1/2	Actual thickness of slate	Myes No	If an enclosed?

## Quality Control Check Repot. Stage: After Column Casting (villas) Quality of centering, rod bending and concreting.

Quanty of centering, for bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good ☐ Avg. ☐ Bad
Quality of starters?	☐ Good ☐ Avg. ☐ Bad
Number and size of honey combs?	☐ High ☐ Medium. ☐ Low
Are the honey combs is slab and columns packed?	☐ Good [ Avg. ☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"	7
Have 6 cubes each for columns and slab casted and numbered for testing?	√Yes  No
Remarks:	2
Curino	
Bunds for curing made on slab? □\X\delta cs □ No	
Bund size is less than 100 sft?	
Drum (200 lts) provided for curing?	
Gunny bags used for column curing?	
Distance of tap from furthest distance that requires curing. (max permitted 100') $g_{0}$	
5	
Is the pressure in the curing pipe more than 15' head? $\square \hat{Y}$ es $\square No$	
Quality of infrastructure for curing.	Bad
Remarks:	

## Quality Control Check Repot. Stage: After Column Casting (villas)

## Columns height, plumb, steel & level marking check.

Notes:

- Mark  $\vee$  for correct or minor mistake which does not require correction Mark  $\times$  for minor mistake that requires minor correction.

  Mark  $\times$  for major mistake that requires correction by replacement or re-fixing. Mark  $\times$  for major mistake that cannot be corrected.

  Tolerance: Plumb 0.25".

Circle actual height of columns if level differs from specified height by more than 1".

20.	19.	18.	17.	16.	15.	14.	13.	12.	11.	10.	9.	8.	7.	6.	5.	4.	3.	2.	1.		S No
																52	22	FS	Ed		Col No.
																72	63	Cr	C		Col type
																8,715,8	8,418	11/11/8	3/14.8	Spec.	Heig
																114.8	8.411	114.8	8.80	Actual	Height in ft
																/	<	<	4	No of rods	Steel
																<	<	<	<	Size of rods	Steel ( v or x)
																X	×	X	メ		Honeycombs
																<	<	<	<	Side 1	Plumb ( or x)
																<	<	<	<	Side 2	( or X)
☐Yes ☐No	☐ Yes ☐ No	□Yes □No	□Yes □No	☐Yes ☐No	☐Yes ☐ No	marked on column?	Reference level														