## Quality Control Check Repot. Stage: After Plastering (Villas)

Villa No.	04	Stage		SI. No.	97388
Company	SVR	Project	200	Phase	-
Prepared by	S. Sums Howard Sign	Sign		Date	13/6/17
Project Manager	A-Sweet.	Sign	Cym,	Date	13/6/17
Previous stage report no.	no.	85627	Report filed and signed by PM?	ed by PM?	Yes No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation:  Stop further work.  Stop further work  Proceed with furtl  Proceed with furtl	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	eport to QC team. Proces and ter submitting ATR on ting corrections pointe ired.	eed only after recheck of QC report to QC team do out in the QC report.	by QC. ATR not required.	

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

### <u>Plastering Check.</u> Notes:

- Mark v for correct or minor mistake which does not require correction

  Mark X for minor mistake that requires minor correction.

  Mark X x for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Rei	19	18	17	16	15	14	13	12	=	10	9	∞	7	6	S	4	ယ	2	-	S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony 2.	Terrace/balcony 1	Lobby 2	Łobby-h	Dining	Drawing	Toilet-4—	Bedroom 4	Toilet 3 K. Toi	Bedroom 3 K. 8 d	Toilet 2 M. Toi	Bedroom 2 M. Bed	Toilet 1 G. Toi	Bedroom 1 G. Bed	Room
			<	1	1	9	<	1	1	<	5	1	1	1	5	5	5	1	K	Skirting Provision
			7	-	1	1	5	1	1	1	7	1	-	<	5	5	5	1	1	Finishing around do frame ( • or ×)
			5	1	1	ſ	1	1	1	(	5	ı	1	(	>	5	5	5	<	Beams & columns finishing ( ✓ or ×)
			-	1	1	1	1	1	1	١	1	1	1	١	)	)	1	1	1	Finishing of lofts ( v or x)
			(		1	1	(	1	1	1	5	-	1	(	3	5	5	<	1	Electrical junctions finishing ( v or x)
			(	1	1	1	1	1	1	1	5	1	1	(	2	5	5	(	<	Window check
			8	1	1	7	•	1	1	1	3	1	1	(	1	5	1	<	1	Tiles provision (✓ or ×)
			1	1	1	1	1	1	1	1	1	1	1	١	)	)	ı	-	1	Sink provision & siz (✓ or 🗙)
			<	1	1	1	5	1	1	1	5	1	1	1	5	5	?	1	5	Grooves for door frames ( v or x)
			1	1	1	ı	(	1	1	1	J	1	1	1	7	)	1	1	1	Balcony & terrace si top finishing <sup>10</sup> ( ✓ or
			1	1	1	•	1	1	1	1	1	1		7	J	3	A	<		Screeding in bathrook utility ( v or x)
			)	١	1	)	1	1	1	١	1	١	١	(	1	ζ	1	(	-	Screeding in 6" above FFL? ( • or ×)

# Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	Good Avg. Bad
Plastering of compound wall & gate pillars ( v or x)	ζ
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Yes No
Plastering quality of parapet walls ( v or x)	ζ
Plastering and finishing of chajjas (✓ or ×)	5
Remarks:	